

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.04.2021

Time: 08:43:54

Page: 1

LKK-

Aig Asa
CLS)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305464981
 REGN NO : SHD3211Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 21.07.2016
 DATE/TIME IN : 21.04.2021 08:55
 ACCIDENT DATE : 20.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	de
0002 04-01-0103-0637-G	FRT BUMPER UPR BRKT LH	1	22.40	20.00	17.92	27.92
0003 04-01-0103-0639-G	FRT BUMPER SIDE BRKT LH	1	24.60	20.00	19.68	27.92
0004 04-01-0103-0574-A	FRT FENDER LH	1	663.00	20.00	530.40	be
0005 04-01-0103-2834-G	FRT FENDER SHIELD LH	1	174.90	20.00	139.92	x an
0006 04-01-0103-0658-G	FRT WHEEL CAP LH	1	217.20	20.00	173.76	ant
0007 04-01-0103-0781-A	HEADLAMP LH	1	1,800.00	20.00	1,440.00	ant

3064.40
 2455.52

SUB-TOTAL : 3,163.44

JOB NATURE

0000 PB	PANEL BEATING	600.00	420
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 17-01	CHECK ALL LIGHTING	40.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	x an

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.04.2021

Time: 08:43:54

Page: 2

LKK-

Ag Asia
CLB

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305464981
REGN NO : SHD3211Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.07.2016
DATE/TIME IN : 21.04.2021 08:5
ACCIDENT DATE : 20.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 L	WHEEL ALIGNMENT	120.00	80	1030
		SUB-TOTAL : 1,400.00		

TOTAL : 4,563.44

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

3485.52

CLB \$2800

63 days

Tanpin 97495746
'WP' 22/4/21 0430
CLB survey after repair
2 days
tanpin@khant.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: