

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: India International Insurance Pte Ltd (HQ)
CCPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/04/2021
Vehicle Reg. No.:	SHC606S	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	09/10/2019
Vehicle Colour:	YELLOW		
Engine No:	G4LEKU363646	Chassis No:	KMHC851CVLU178999
Odometer:	115035 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS**Amount**

Parts	1,236.32
Miscellaneous Items	11.00
Labour	840.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	2,087.32
+ GST 7.00% (\$)	146.11
Nett Amount (\$)	2,233.43

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2021)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC606S/21/04/2021 15:21**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	By *459.40 FL
2	1		*REAR BUMPER CLIPS	20.00	0.00	X *22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	de *451.25 FL
4	1		*REAR BUMPER LOWER CTR MOULDING	20.00	0.00	ay *155.00 FL
5	1		*REAR BUMPER FOG LAMP	20.00	0.00	X *201.50 FL
6	1		*REAR NUMBER PLATE	0.00	0.00	an *25.00 F
7	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	an *180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,494.15
- List Item Discount on L Items (\$\$)	257.83
Total Parts (\$\$)	1,236.32

ComfortDelGro Engineering Pte Ltd/SHC606S/21/04/2021 15:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New 350	400.00
2	SPRAY PAINTING CHARGE	New 250	300.00
3	WIRING CHARGE	New X	60.00
4	REMOVE AND REFIX REVERSE SENSOR	New 30	80.00
Gross Labour Cost (\$\$)			840.00

ComfortDelGro Engineering Pte Ltd/SHC606S/21/04/2021 15:21. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749
 WP, 22/4/21 0440
 2 days
 P/P Kony before part
 Tanpin (Kony) -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 21.04.2021 14:52 Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO.:305464917

STOMER

/MS CITYCAB PTE LTD
STOMER NO. 7010070
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)
(P)

COUNT CARD NO.

REGN NO:

SHC 606S

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN
21.04.2021 09:45

YR OF MANU.

09.10.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU178999

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 20.04.2021
NATURE: 3P 20.04.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Weldgement Slip

Exit Pass

Vehicle No.: SHC 606S YY III

Vehicle No.: SHC 606S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard