

Thank You!

You have successfully applied to transfer your vehicle. The next owner has to confirm the transfer by 15 Apr 2019.

Vehicle Details

Vehicle No.:

Vehicle Type:

SMK3693T

N18 - Passenger (Co) Company Car (Single Rate)

Vehicle Attachment 1:

Vehicle Scheme:

No Attachment

Normal

Vehicle Make:

Vehicle Model:

B.M.W.

335I A

Chassis No.:

Engine No.:

WBAWL72030PZ84515

N54B30A05816979

Next Owner's Details

ID Type:

ID:

Company

199206992R

Name:

Mobile No.:

MOTOR-WAY CREDIT PTE LTD

97265535

Transaction Details

Business Transaction Ref. No.:

Business Transaction Date:

20190410211323337142

10 Apr 2019

Business Transaction Time:

21:13:23

Printed on 10 Apr 2019 21:14:19

Copyright © Land Transport Authority of Singapore 2018

Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0461118

Date of Report

: 10/12/2018

To: Ms Jacqueline Chen

35 Chu Lin Road Singapore 669929 Date of Assignment ; 19/11/2018

Report requested by Ms Jacqueline Chen

4 14/11/2018

Date of Accident Date of Inspection

: 19/11/2018

Claim No.

Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: ET128B

Engine Capacity (cc) 3 2979cc : 148987km

Make & Model

BMW 335i (A) : 11/08/2009

Mileage (km)

Chassis / Frame No. : WBAWL72030PZ84515

Date of Registration Colour

: Met. Silver

Engine No.

: N54B30A05816979

TYRE CONDITION

Front LH

: 6 mm : Michelin Front RH

: 6 mm

Make

Michelin

Rear LH

: 6 mm

Rear RH

: 6 mm

Make

Make

: Michelin

Make

: Michelin

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

: Serviceable

Steering Apparent Engine Modification

. Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Yap Lee Motor

1, Kaki Bukit Ave 6, Blk B, #01-26, Autobay @ Kaki Bukit, Singapore 417883

ASSESSMENT

Repairer's Estimate

Revised Amount

: \$ 11,718.05

Less Excess

: \$ 9,927.15

: \$: \$

Recommended Reserve

7,940.00 (Lump Sum)

Estimated Normal Period of Repairs

: 5 Working Days

Disclaimer: This report is intended for the exclusive use of the addresses solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.