



1 of 4

Report No. T/20210418/2089

Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456

Tel No: 1800-8522999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/04/2021 21:30			Vide Report No.:	Station Diary No. 52		
Informan	t's Partici	ulars				
Name of Informant: SHE ZESI			Address: 91 YISHUN AVENUE 1 #12-17 SINGAPORE 769135			
ID Type / ID No.: NRIC NO / S8519855F			Contact No.: Home/Office:	Mobile: 90497270		
Nationality: SINGAPORE CITIZEN		EN	Email:			
Sex: Female	Age: 35	Date of Birth: 07/07/1985	Type of Informant: Driver			
Race: Chinese			Language: English	Institution / School Name:		
Occupation: UNEMPLOYED			Driving Licence Informatio Class:	n: Date of Expiry:		

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/04/2021 11:00	Type of Location Straight Road	
Location: JALAN SELAS	SEH				
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume:	
Dual Carriage	***uy				

hicle Invo	lved			9000	
Туре	Make	Model	Color	Condition	No of Passenge
Car	VOLKSWAGO N	SHARAN 2.0 TSI 7N24MY	Blue	Seriously	
Car	MAZDA	MAZDA5 5- DOOR WAGON	White	Slightly Damaged	0
	Type Car	Car VOLKSWAGO N	Type Make Model Car VOLKSWAGO SHARAN 2.0 N TSI 7N24MY Car MAZDA MAZDA5 5-DOOR	Type Make Model Color Car VOLKSWAGO SHARAN 2.0 N TSI 7N24MY Car MAZDA MAZDA5 5- DOOR WAGON	Type Make Model Color Condition Car VOLKSWAGO SHARAN 2.0 Blue Seriously





Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999

2 of 4 Report No. T/20210418/2089

CONTINUATION OF REPORT

Details of Perso	in Involved	51 - 0 - 0 - 0 - 0		early litter		
Any Pedestrian I	The state of the s				S SIN H	
No. of Pedestriar	Use of Pedestrian Crossing: NA					
Driver		TOTAL TOTAL		accti tai	1 01000	Miles Salara
Name	SHE ZESI			ID No		S8519855F
Related Vehicle	SKR7576J (Car)			Contact No.		90497270
Hospital/Clinic	PHEONIX MEDICAL GROUP PTE LTD			Class of Driving Licence & Expiry Date		Class: 3A Date of Expiry: NIL
Date Treatment	18/04/2021 Date Disc					
No. of Days granted Medical Leave 03			Degree of			
Driver						
Name	John			ID No		NIL
Related Vehicle	SMR703G (Car)		Contact No.		97812733	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: 3A Date of Expiry: NIL	
Date Treatment NIL			Date Disch		NIL	
No. of Days grant	ted Medical Leave	NIL	Degree of		NIL	

Brief Details.

On the 18/04/2021 at about 1100hrs, I was driving my car bearing plate number "SKR7576J" along Seletar Hills Drive. I made a stop at the stop line of Jalan Selaseh near Jalan Selaseh Playground before heading straight towards Seletar Hills Drive. As I saw no vehicles approaching, I drove off the stop line and as I was driving pass the clear road, my father at the rear seat told me that there is a oncoming car approaching towards our direction at a high speed. Before I could react, the car bearing plate number "SMR703G" had collided onto my car.

There were a lot of witness at the incident and some of them had already informed the ambulance. As the paramedics arrived, they made a check on my family and on the driver of "SMR703G". They informed that everyone is in good condition and did no one was being conveyed. The Traffic Police then arrived at scene, the officers then took down both the driver's particulars and advised us to lodge a police report for insurance claim purposes as no one was seriously injured. However I did not receive any case card for this accident. And there were a total of 2 Airbags being deployed from my car.

The damages on my car bearing plate number "SKR7576J" is as follows: On the left side, the 2 tyres front and rear were broken and punctured. On the right side, both my driver's and passenger's door was seriously damaged and it is not in working condition anymore.

The damages on the other car bearing plate number "SMR703G" is as follows: Minor dents and paint scratches on the front left bumper.





T/20210418/2089

Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999

CONTINUATION OF REPORT

3 of 4 Report No. T/20210418/2089

The tow department of Volkswagen then came to tow away my car for servicing as it was damaged and the car was not in driving condition any more. As the Volkswagen workshop is closed for today, they would be assessing my car on the next working day. Therefore I am not sure of the repair fees.

I wish to state that as I sustained minor injures such as sprains and muscle pains at the right shoulder and along my right elbow area. I then consulted the a doctor from Pheonix Medical Group Pte Ltd on the same day dated on the 18/04/2021. I then obtained a 3-day MC from the clinic. On my passenger seats which consisted my Father and my Son, did not sustain any injures. Therefore they did not require any medical consultation. I also have a Car Dash Cam located at the front interior of my car. I have the SD card under my safe keeping for record purposes and I am lodging this report for insurance claim purposes.





Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999 4 of 4 Report No. T/20210418/2089

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
SCSGT(1) PRABAKARAN GOVINDHAN	Sin
Signature Of Interpreter:	Date/Time:
Not applicable	18/04/2021 21:30
Officer In Charge Of Case: TP / GIT /	Classification Of Case:
SI MOHAMMAD ABDILLAH BIN PALIL	TN 30 m
Contact No.: 65476246	CAR YOU.
Authentication Stamp	(A)