


(08/11/13) wef
ASS. REC. BY: Posun

REF: CS/MSH 21005081/R1983
ASSIGNMENT

7957

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKR 7576J
at Workshop m/s. VANTAGE AUTOMOTIVE
of 305, ALEXANDRA RD
Insured: MSU
Policy No. 1001402263
Claims No. 256212
Sum Insured: _____ Excess: TBA 1500
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 102k
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 14 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SKR 7576J Yr Regn: 2017 / MM
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Volkswagen SHARAN 2.0TSI c.c. 1984
Colour: BLUE A/C: Insured / Std / NI / NA
Sp. Reading: 67128 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WVWZ2267N24V236794
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/50R17
R: _____
BS / DUN / EXNOVA / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front
R/Bal. 6 mm
L/Bal. 6 mm
D.O.A. 18/04/21
Rear
R/Bal. 6 mm
L/Bal. 6 mm
D.O.I. 23/04/21
Survey held at VANTAGE
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair 1.1.7 - 38K</u>
26/4/2021@4.26pm	Revert to Richard Ang via Merimen.
27/4/2021@8.22am	Elaine Ngu informed C/A via Merimen.
27/4/2021@9.45am	Informed Andy C/A & ex:\$1500/- by email.
02/12/21@5.23pm	confirmed with Katherine final fig \$25897.54, 14 days. (Red \$32610.79, 56%)
07/12/21@5.01pm	re-confirmed with Katherine final fig \$24217.54, 14 days. (Red \$34290.79, 59%)

Date/Time, File Pass to? ☐ : Preli. Report
1) 07/12 Typist ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 14
Resurvey No. of Trip: 4

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:
Transportation: _____
S + RS, SI
Photos
Others
TOTAL

Report Format : MER-OD
Lump Sum / I.B.I: (\$ 24217.54)

GST Registration No. M2-0000551-1

E S T I M A T E

Page No. : 1 of 3

Estimate No. : B9 5021
 Date Estimated : 22/04/2021
 Prepared By : Andy Ooi Lee Keong

- ESTIMATE REPAIR FOR -

Tan Kok Cheng
 114 Saraca Road

Singapore 807410

- ACCOUNT - 24748
 MSIG Insurance (Singapore) Pte Ltd
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR7576J	WVWZZZ7NZHV236794	31/05/2017	VOLKSWAGEN S	0

DESCRIPTION

VALUE

TO CONDUCT OD CLAIM - MSIG INS. DOA.18/04/2021

0.00

LABOUR TO REMOVE & REPLACE FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH, CENTRE DOOR PILLAR RH, REAR FENDER RH, FRONT FENDER RH, FRONT BUMPER, REAR BUMPER & FLOOR PANEL RH.

1500 3,000.00

LABOUR TO RESPRAY & PUTTY FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH, CENTRE DOOR PILLAR RH, REAR FENDER RH, FRONT FENDER RH, FRONT BUMPER, REAR BUMPER & FLOOR PANEL RH.

1000 2,000.00

TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT CODES.

250 480.00

TO CONDUCT FULL WHEEL ALIGNMENT.

100 350.00

TO REMOVE & INSTALL FRONT LH SUSPENSION INSPECTION AND REPLACE DAMAGED PARTS.

250? 380.00

TO REMOVE & INSTALL REAR LH SUSPENSION, REAR LH AXLE & CONTROL SYSTEM TO FACILITATE THE WORK ON REPAIR BENCH.

250? 380.00

07/12/21 @ 5:01pm re-confirmed with Katherine final fig \$24217.54, 14 days. (Red \$34

TO REMOVE & INSTALL REAR SUSPENSION, REAR AXLE AND CONTROL SYSTEM FOR INSPECTION AND REPLACE DAMAGED PARTS.

X 580.00

TO MOUNT VEHICLE ON REPAIR BENCH TO FACILITATE RE-ALIGNMENT OF CHASSIS ACCORDING TO SPECIFICATION. (photo)

1,680.00

TO REMOVE & INSTALL REAR HAT-TRAY, REAR SEAT, CARPET & ROOF TOP LINING TO FACILITATE THE CUTTING OF THE CENTRE, PILLAR RH, PILLAR LH & ROCKER PANEL RH.

300 600.00

TO REMOVE & INSTALL FRONT & REAR RH WINDOW GLASS INCLUDING TO CONDUCT WATER LEAK TEST.

200 280.00

TO REPLACE LEATHER SEAT COVERS ON FRONT SEAT RH INCLUDING TO REMOVE AND INSTALL SEATS.

200 480.00

TO TRANSFER LOCK MECHANISM FRONT & REAR DOOR (RH), DOOR TRIM BOARD AND WINDOW REGULATOR MOTOR.

200 760.00

GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **B9 5021**
Date Estimated : **22/04/2021**
Prepared By : **Andy Ooi Lee Keong**

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR7576J	WVWZZZ7NZHV236794	31/05/2017	VOLKSWAGEN S	0

DESCRIPTION	VALUE
TO CHECK ELECTRICAL WIRING SYSTEM AND TO RESET AIRBAG WARNING LIGHT ON.	180 380.00
TO REPLACE BOTH FRONT & REAR SEAT BELT TENSIONER.	200 560.00
TO REPLACE ROOF TOP HEADLINING AND HEAD AIR BAG.	250 680.00
TO REPLACE FRONT RH SEAT AIRBAG.	250 680.00
TO CARRY OUT BODY CAVITY PRESERVATION.	150 270.00
TO SUPPLY 2PCS TYRE - 225/50R17	? 280.00

Total Labour 1: **15,220.00**

DESCRIPTION	QTY	PRICE	DISC	VALUE
FRONT BUMPER LH LOWER COVER 2 ?	1	133.18	0.00	133.18
FRONT DOOR RH 1 ✓	1	1,411.78	0.00	1,411.78
FRONT DOOR SEAL 1 ✓	1	175.46	0.00	175.46
FRONT DOOR CHROME . ?	1	129.37	0.00	129.37
FRONT DOOR HINGES RH (UPPER) ?	1	53.77	0.00	53.77
FRONT DOOR HINGES RH (LOWER) ?	1	53.77	0.00	53.77
FRONT DOOR WINDOW LIFTER ?	1	171.48	0.00	171.48
FRONT DOOR WINDOW MOTOR ?	1	157.75	0.00	157.75
FRONT WING MIRROR HOUSING 1 ✓	1	529.68	0.00	529.68
FRONT WING MIRROR COVER 1 ✓	1	60.97	0.00	60.97
FRONT WING MIRROR GLASS 1 ✓	1	124.75	0.00	124.75
REAR DOOR RH SEAL 1 ✓	1	292.03	0.00	292.03
REAR DOOR RH CHROME . ?	1	133.95	0.00	133.95
REAR DOOR RH HINGE . ?	1	159.90	0.00	159.90
REAR DOOR RH INNER SEAL 1 ✓	1	197.37	0.00	197.37
REAR DOOR RH WINDOW LIFTER . ?	1	179.27	0.00	179.27
REAR DOOR RH MOTOR . ?	1	157.75	0.00	157.75
REAR DOOR RH LOCK . ?	1	382.68	0.00	382.68
RR DOOR POWER LOCK MOTOR ?	1	334.18	0.00	334.18
REAR QUARTER GLASS RH 1 ✓	1	291.36	0.00	291.36
ROCKER PANEL WITH B-PILLAR RH 1 ✓	1	1,011.82	0.00	1,011.82
REAR DOOR TOP CHROME RH . ?	1	142.25	0.00	142.25
FRONT DOOR TOP CHROME RH . ?	1	186.29	0.00	186.29
CURTAIN ROOF AIRBAG RH 1 ✓	1	1,068.05	0.00	1,068.05
ROOF LINING 1 ✓	1	1,178.13	0.00	1,178.13
A-PILLAR INNER COVER RH UPPER . ?	1	160.60	0.00	160.60
A-PILLAR INNER COVER RH -LOWER . ?	1	22.78	0.00	22.78
FRONT SEAT AIR BAG RH 1 ✓	1	711.23	0.00	711.23
WIRE HARNESS . ?	1	156.33	0.00	156.33
PADDING ITEM . ?	1	212.44	0.00	212.44

Vantage Automotive Limited

Vision of Vantage Automotive Limited)
Business Registration No. 192600045M GST Registration No. M2-0000551-1
Alexandra Road
9942 Singapore
Tel : 6272 8828
Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : **B9 5021**
Date Estimated : **22/04/2021**
Prepared By : **Andy Ooi Lee Keong**

Page No. : **3 of 3**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR7576J	VWVZZZ7NZHV236794	31/05/2017	VOLKSWAGEN S	0

DESCRIPTION	QTY	PRICE	DISC	VALUE
FRONT SEAT LEATHER RH <i>turn</i>	1	898.70	0.00	898.70
FRONT SEAT RAIL RH <i>X</i>	1	750.19	0.00	750.19
FRONT SEAT BELT RH <i>AG</i>	1	430.46	0.00	430.46
FRONT SEAT BELT LH <i>AG</i>	1	430.46	0.00	430.46
REAR SEAT BELT RH <i>AG</i>	1	430.46	0.00	430.46
B-PILLAR INNER COVER RH UPPER <i>?</i>	1	141.99	0.00	141.99
AIRBAG STICKER (RH B-PILLAR)	1	10.86	0.00	10.86
AIRBAG CONTROL UNIT MODULE <i>re</i>	1	980.07	0.00	980.07
RH FRONT RIM <i>X</i>	1	457.63	0.00	457.63
RH REAR RIM <i>X</i>	1	457.63	0.00	457.63
LH FRONT RIM <i>sur</i>	1	457.63	0.00	457.63
LH REAR RIM <i>sur</i>	1	457.63	0.00	457.63
LH REAR SHOCK ABSORBER <i>?</i>	1	191.71	0.00	191.71
LH REAR WHEEL BEARING <i>?</i>	1	339.49	0.00	339.49
RH REAR SHOCK ABSORBER <i>X</i>	1	191.71	0.00	191.71
RH REAR WHEEL BEARING <i>X</i>	1	339.49	0.00	339.49
LH FRONT SHOCK ABSORBER <i>X</i>	1	223.75	0.00	223.75
LH FRONT WHEEL BEARING <i>?</i>	1	299.30	0.00	299.30
LH FRONT LOWER ARM <i>?</i>	1	297.06	0.00	297.06
LH FRONT UPPER ARM <i>?</i>	1	300.62	0.00	300.62
LH TIE ROD <i>?</i>	1	58.36	0.00	58.36
STEERING RACK AND PINION <i>X</i>	1	3,329.49	0.00	3,329.49
CROSS MEMBER <i>X</i>	1	908.57	0.00	908.57
LH REAR KING PIN <i>?</i>	1	420.40	0.00	420.40
LH REAR TRAILING ARM <i>?</i>	1	157.83	0.00	157.83
RH REAR KING PIN <i>?</i>	1	420.40	0.00	420.40
RH REAR TRAILING ARM <i>?</i>	1	157.83	0.00	157.83
LH FRONT KING PIN <i>?</i>	1	386.37	0.00	386.37
Total Parts :				23,906.46

Gasul
Hp 900/10068
10-11 days
EXCESS: 1500
Revert
Resurvey before
paint
23/04/21
@ 1530

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp

Date

Labour 1	:	15,220.00
Parts	:	23,906.46
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,738.85
Grand Total	:	41,865.31

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/04/2021 10:52 (SGT)
Date of Accident	18/04/2021 11:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JALAN SELASEH
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR7576J
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN KOK CHENG
NRIC No	SXXXX795F
Email Address	SHEZESI@GMAIL.COM
Mobile Phone No	(Phone) +65-98164882
Alternative Phone No	+65-90497270

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Sharan
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	A 28967446 AVW
Cover Note Number	-

DRIVER

Name of Driver	SHE ZESI
NRIC No	SXXXX855F

Date Of Birth	07/07/1985
Occupation	Indoor
Date Of Driving Pass	23/11/2005
Driving experience	15 YEARS AND 5 MONTHS
Gender	Female
Mobile Number	(Phone) +65-90497270
Alt. Phone Number	-
Email Address	SHEZESI@GMAIL.COM
Address	91 YISHUN AVE 1
Address complement	#12-17
Postcode	769135
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	SEAH AH LEK
Gender	Male

PASSENGER 2

Name	TAN JI WEI JONSON
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Yishun South Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18008522999
Alt. Police Station Phone No	(Fax) +65-68522239
Police Station Address	32 Yishun Street 81 Singapore 768456
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT/SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMR703G
Vehicle Manufacturer	Mazda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	JOHN
Contact Number	(Phone) +65-97812733
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TAN JI WEI JONSON
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKR7576J
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20210418/2089

1 of 4

Report No. T/20210418/2089

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
18/04/2021 21:30

Vide Report No.:

Station Diary No.:
52

Informant's Particulars

Name of Informant: SHE ZESI			Address: 91 YISHUN AVENUE 1 #12-17 SINGAPORE 769135		
ID Type / ID No.: NRIC NO / S8519855F			Contact No.: Home/Office: Mobile: 90497270		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 35	Date of Birth: 07/07/1985	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: UNEMPLOYED			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/04/2021 11:00	Type of Location: Straight Road
Location: JALAN SELASEH				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: (Red)
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKR7576J	Car	VOLKSWAGO N	SHARAN 2.0 TSI 7N24MY	Blue	Seriously Damaged	2
SMR703G	Car	MAZDA	MAZDA5 5- DOOR WAGON 2.0L SP.6EAT	White	Slightly Damaged	0



Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SHE ZESI	ID No.	S8519855F
Related Vehicle	SKR7576J (Car)	Contact No.	90497270
Hospital/Clinic	PHEONIX MEDICAL GROUP PTE LTD	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	18/04/2021	Date Discharge	18/04/2021
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	John	ID No.	NIL
Related Vehicle	SMR703G (Car)	Contact No.	97812733
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 18/04/2021 at about 1100hrs, I was driving my car bearing plate number "SKR7576J" along Seletar Hills Drive. I made a stop at the stop line of Jalan Selaseh near Jalan Selaseh Playground before heading straight towards Seletar Hills Drive. As I saw no vehicles approaching, I drove off the stop line and as I was driving pass the clear road, my father at the rear seat told me that there is a oncoming car approaching towards our direction at a high speed. Before I could react, the car bearing plate number "SMR703G" had collided onto my car.

There were a lot of witness at the incident and some of them had already informed the ambulance. As the paramedics arrived, they made a check on my family and on the driver of "SMR703G". They informed that everyone is in good condition and did no one was being conveyed. The Traffic Police then arrived at scene, the officers then took down both the driver's particulars and advised us to lodge a police report for insurance claim purposes as no one was seriously injured. However I did not receive any case card for this accident. And there were a total of 2 Airbags being deployed from my car.

The damages on my car bearing plate number "SKR7576J" is as follows: On the left side, the 2 tyres front and rear were broken and punctured. On the right side, both my driver's and passenger's door was seriously damaged and it is not in working condition anymore.

The damages on the other car bearing plate number "SMR703G" is as follows: Minor dents and paint scratches on the front left bumper.



SINGAPORE POLICE FORCE



T/20210418/2089

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

3 of 4

Report No. T/20210418/2089

CONTINUATION OF REPORT

The tow department of Volkswagen then came to tow away my car for servicing as it was damaged and the car was not in driving condition any more. As the Volkswagen workshop is closed for today, they would be assessing my car on the next working day. Therefore I am not sure of the repair fees.

I wish to state that as I sustained minor injuries such as sprains and muscle pains at the right shoulder and along my right elbow area. I then consulted the a doctor from Pheonix Medical Group Pte Ltd on the same day dated on the 18/04/2021. I then obtained a 3-day MC from the clinic. On my passenger seats which consisted my Father and my Son, did not sustain any injuries. Therefore they did not require any medical consultation. I also have a Car Dash Cam located at the front interior of my car. I have the SD card under my safe keeping for record purposes and I am lodging this report for insurance claim purposes.

Require PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	795F
Vehicle No.:	SKR7576J
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Apr 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI 7N24MY
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	DED012358
Chassis No.:	WVWZZZ7NZHV236794
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$34,811.00
Original Registration Date:	31 May 2017
First Registration Date:	31 May 2017
Transfer Count:	0
Actual ARF Paid:	\$40,736.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2027
PARF Rebate Amount:	\$30,552.00
COE Expiry Date:	30 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$33,154.00
Total Rebate Amount:	\$63,706.00

The information contained herein is correct as at 26 Apr 2021

OK



CONVINCE YOUR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more

SGCARMART
CONNECT
DRIVING BUYERS & SELLERS

SEARCH

Volkswagen Sharan

Price Range

Depreciation

2017

Vehicle Type



Search

View All

Advanced Search

Home » Used Cars » Direct Owners » Volkswagen Sharan 2.0A TSI Sunroof

Volkswagen Sharan 2.0A TSI Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Price \$99,900

Depreciation

\$13,420 /yr

View models with similar depre

Reg Date

30-Mar-2017

(5yrs 11mths 3days COE left)

Mileage

77,000 km (18.9k /yr)

Manufactured

2017

Road Tax

\$1,194 /yr

Transmission

Auto

Dereg Value

\$62,143 as of today (change)

OMV

\$34,816

COE

\$53,300

ARF

\$40,743

Engine Cap

1,984 cc

Power

162.0 kW (217 bhp)

Curb Weight

1,790 kg

No. of Owners

1

Type of Vehicle

MPV

Features

View specs of the Volkswagen Sharan (2011)

Description

Single Owner, Best 7 Seater Family Car, Just Replaced 4 New Tires In Q4 2020 [225/50R17], Attractive Interior Colour Instead Of The Usual Black.

Category

PARF Car, Direct Owner Sale

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 02-Apr-2021 | Last Updated on: 22-Apr-2021

Upfront Payment

» more Financial info

Transfer Fee

\$25

Down Payment

\$39,960 (change) Maximum 60% Loan

1st Inst

SHORTLISTED

HISTORY

\$968 Based on 2.48% interest rate

Get your loan approved now in 60 seconds. T&Cs apply.
Learn More

Compare




OCBC Bank



Preferred Viewing Area

100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Report

More

Seller Information

Contact Person(s)

Jason