## OMFORT TRANSPORTATION PTE LTD REPAIR ESTIMATE

Vehicle No.: SHA4353E : TOYOTA Make

: PRIUS Model DOA 16/P/06: Date Insurance: 21.04.21

MVA

NTUC **JUMANI** 

Qty	Parts Description / Labour	Qty	Unit Price	Amount
	REAR BUMPER ASSY	1		\$458.60
2	TAILLAMP LOWER RH	1		un × \$548.40
3	REAR BUMPER CLIPS	10		ha = \$22.00
	SEAL REAR BUMPER RH	1		\$148.40
5	RETAINER REAR BUMPER RH	affect of the literature of the desired of the second		nn X \$94.80
	Rear brimper 552.60 CM/ SUB TOTAL LESS 20%			\$1,272.20
	quant che DISCOUNTED TOTAL		1033,20	\$318.05
	DISCOUNTED TOTAL			\$954.15
212,02000.2		Samuel a combination and	174.90	
	RERA BUMPER MAT			ner \$50.00
ľ	CERA BUMPER MAI	1	50	\$50.00
matus q		oca antian compositi	de la resemble de la resemble de la constante	
hadana a II. s	e province de la companya de la comp	Liendrich weben bereich	le l'exerce es en electron e	\$50.00
L	abour Charge			da - i
	\ 1		1	
P.	ANEL BEATING		2.0	353
Si	PRAYPAINT		680	\$600.00
R)	EMOVE/REFIX REVERSE SENSOR		40	30- \$80.00
	Tauphn 97495745			7 - \$80.00
-}-				
	mp 214/218 1433		1504.90	
	115 Nisnin outher report		1	1
			45\$ 200	-1
	Tours !		01	
1	Taufher 9795745  "np 21/4/218 1433  L/S Misney affer report  Lags  furfrise / Whart.com,		1504.90 48\$1200 2dys	
167 E 1 2 FT 20 11.3 L 1 2 12.1	TOTAL LABOUR	r in german ann ar a ge	#	\$1,080.0
erikasi Alban	ESTIMATE TOTAL	Protection States and American	F.S. of Condition of the Association of the Condition	\$2,084.1
il.	130	and an activities to the con-	e a se esta a carrelle e a carrel a re-	Ψ2,004.
				-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: