

|   |   |   |        |   |   |   |   |      |   |   |   |   |                      |             |
|---|---|---|--------|---|---|---|---|------|---|---|---|---|----------------------|-------------|
| ⏪ | < | 1 | of 2 ? | > | ⏩ | ↺ | ↻ | 100% | ▼ | 📄 | ✓ | 🖨 | <input type="text"/> | Find   Next |
|---|---|---|--------|---|---|---|---|------|---|---|---|---|----------------------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                           |                        |                          |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|------------------------|--------------------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                               |                                           |                        |                          |  |
| MSG INSURANCE (SINGAPORE) PTE LTD                                                                                                      |                                           |                        | Ref: CS/MSG21005089/Utt3 |  |
| 4 SHENTON WAY #21-01,SGX CENTRE 2                                                                                                      |                                           |                        | Date: 23/04/2021         |  |
| SINGAPORE 068807                                                                                                                       |                                           |                        | Code: MSG                |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                           |                        |                          |  |
| <b>Insured Veh.</b>                                                                                                                    | SMD 9406D                                 | <b>Veh. Inspected</b>  | SMV 6024Y                |  |
| <b>Policy No.</b>                                                                                                                      | 1001528816                                | <b>Coverage (\$)</b>   | 0.00                     |  |
| <b>Claim No.</b>                                                                                                                       |                                           | <b>Excess (\$)</b>     | 0.00                     |  |
| <b>Assign From</b>                                                                                                                     | CRYSTAL LEE                               | <b>Assign Date</b>     | 23/04/2021               |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                           |                        |                          |  |
| <b>Make &amp; Model</b>                                                                                                                |                                           | <b>c.c</b>             | 0                        |  |
| <b>Engine No.</b>                                                                                                                      | HIDDEN                                    | <b>Year of Reg.</b>    |                          |  |
| <b>Chassis No.</b>                                                                                                                     |                                           | <b>Colour</b>          |                          |  |
| <b>Odometer</b>                                                                                                                        | -                                         | <b>Steering</b>        |                          |  |
| <b>Brakes</b>                                                                                                                          |                                           | <b>Modification</b>    |                          |  |
| <b>General</b>                                                                                                                         |                                           |                        |                          |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                           |                        |                          |  |
|                                                                                                                                        | <b>Size</b>                               | <b>Make</b>            | <b>Balance</b>           |  |
| <b>R/H Front Tyre</b>                                                                                                                  |                                           |                        | mm                       |  |
| <b>L/H Front Tyre</b>                                                                                                                  |                                           |                        | mm                       |  |
| <b>R/H Rear Tyre</b>                                                                                                                   |                                           |                        | mm                       |  |
| <b>L/H Rear Tyre</b>                                                                                                                   |                                           |                        | mm                       |  |
| <b>4. Description of Damages</b>                                                                                                       |                                           |                        |                          |  |
|                                                                                                                                        |                                           |                        |                          |  |
| <b>5. General Information</b>                                                                                                          |                                           |                        |                          |  |
| <b>Accident Date</b>                                                                                                                   | 23/04/2021                                | <b>Inspection Date</b> | 26/04/2021               |  |
| <b>Survey held at</b>                                                                                                                  | Blk 15 Kaki Bukit Road 4, #01-Bartley Biz |                        |                          |  |
| <b>Repairer</b>                                                                                                                        | ZOOM AUTOWERKS PTE LTD                    |                        |                          |  |
| <b>5a. Remarks</b>                                                                                                                     |                                           |                        |                          |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                           |                        |                          |  |