



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:LYNN

Ref: CC4/ASM21005093/Kpa3q2
Date: 29/11/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFC 2866T	Veh. Inspected	SFN 7828M
Policy No.	GA441223	Coverage (\$)	0.00
Claim No.	S1M038MG	Excess (\$)	0.00
Assign From		Assign Date	23/04/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200K (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDB2110412B392839	Colour	METALLIC GREY
Odometer	107739 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R16	MICHELIN	2 mm
L/H Front Tyre	225/55 R16	MICHELIN	2 mm
R/H Rear Tyre	225/55 R16	MICHELIN	3 mm
L/H Rear Tyre	225/55 R16	MICHELIN	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/04/2021	Inspection Date	26/04/2021
Survey held at	GUAN HIN MOTOR WORKSHOP BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**