

ASS. REC. BY: NA2 REF: CC4/AIA 21005120 NPA3 DERRICK L13

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
LMS	RIS

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHD 14852 Yr Regn: 17 OCT 2017  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: HYUNDAI 130 C.C. 1,582  
 Colour: SILVER A/C: Insured / Std / NI / NA  
 Sp. Reading: 387,072 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JMAD2814V1A1 141988  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / SRim / STD A/Rim or  
 Tyre Size: F: 145/65 R15  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / tyre brands  
 TOYO / YOKO or MICCF MAXXUS

Front Rear  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 22/4/2021 D.O.I. 26/4/2021

Survey held at PREMIER CHANGE  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
FRONT OFF-SIDE NEAR-SIDE

The U/C / Chassis frame / Body Structure affected due to collision.

JM L13

Date / Time	Action / Instruction
<u>4/5/2021</u>	<u>FINALIZED LUMP SUM REPAIR \$790.00 / 2 REPAIR DAY</u>

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS, SI

Photos

Others

TOTAL

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H  
Owner ID Type: Company  
Owner Name: PREMIER TAXIS PTE. LTD.  
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
Mailing Address: -  
Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHD1485L  
Previous Vehicle No.: -  
Effective Date of Ownership: 17 Oct 2017  
Original Regn Date: 17 Oct 2017  
Registration Date: 17 Oct 2017  
Year of Manufacture: 2017  
Vehicle Type: Public Transport Taxi (Motor Car)  
Vehicle Scheme: Taxi (Company)  
Vehicle Attachment 1: Air-Con (Taxi)  
Vehicle Attachment 2: -  
Vehicle Attachment 3: -  
Vehicle Make: HYUNDAI  
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
Primary Colour: Silver  
Secondary Colour: -  
Passenger Capacity: 4  
Chassis No.: TMAD281UVHJ141988  
Engine No.: D4FBHZ172981  
Engine Capacity/Power Rating: 1582 cc / -  
Maximum Power Output: 100.0 kW (134 bhp)  
Propellant: Diesel  
Max Unladen Weight: 1496 kg  
Maximum Laden Weight: 1940 kg  
Open Market Value: \$20,019.00