

Our Job Ref No : 305465422  
Date : 27/04/21

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Attn : NAZ

Vehicle Reg No. : SHC7088R

Fax :

Date of Accident : 23/04/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: TOKIO --- SLM2849U  
##
- The finalized amount shall be:
  - Spare Parts after List discount
  - Labour Charges

**Total for Part-By-Part Repair Cost**

  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$1,950.00  
**Final Lumpsum Repair cost**
- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance. We confirm the estimates and finalized amount

Signature : [Signature]  
Name : JUMANI  
Tel : 62148315  
Fax : 65468156

Signature : [Signature]  
Name : NAZ LKK  
Date : 28/4/2021

#### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	--	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No 199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

Tokio Marine Insurance Singapore Ltd (HQ)

Jumani

(Usum)

INSURER:

CCPL

Singapore

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/04/2021
Vehicle Reg. No.:	SHC7088R	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	21/04/2016
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4FDGU621269	Chassis No:	KMHLB41UMGU088844
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

## COST OF CLAIMS

	Amount
Parts	2,826.40
Miscellaneous Items	11.00
Labour	1,300.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>4,137.40</b>
<b>+ GST 7.00% (S\$)</b>	<b>289.62</b>
<b>Nett Amount (S\$)</b>	<b>4,427.02</b>

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## DETAILS

Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2021)  
 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)  
 Repairer's (Price-denominated Standard List)  
 Print Code: **ComfortDelGro Engineering Pte Ltd/SHC7088R/26/04/2021 10:07**  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	20.00	0.00	*1,025.20 FL
2	1		*FRT BUMPER SIDE BRACKET LH	20.00	0.00	*44.80 FL
3	1		*FRT FENDER LH	20.00	0.00	*663.00 FL
4	1		*HEADLAMP ASSY LH	20.00	0.00	*1,800.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,533.00
- List Item Discount on L Items (S\$)	706.60
Total Parts (S\$)	2,826.40

ComfortDelGro Engineering Pte Ltd/SHC7088R/26/04/2021 10:07. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

Particulars

Amount

OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

### Labour Items

1	PANEL BEATING	New	600.00
2	SPRAYPAINT	New	600.00
3	CHECK WIRING	New	50.00
4	TUFF KOTE	New	50.00

Gross Labour Cost (S\$)

1,300.00

ComfortDelGro Engineering Pte Ltd/SHC7088R/26/04/2021 10:07. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NAG CLK  
LIS

26/4/2021 1245

3 DMD

CHECK ITEM PHOTO

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: