

ASS. BY:

REF:

CS / SMR 21005133 / Day 3

ASSIGNMENT

COE Dec 2026

From: _____ Date: _____

Estimate Cost: _____

OD / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: SHD 3846R

at Work on: _____

of _____

Insured SHF 693

Policy # _____

Claimed Tax / 04 / 21 / 2064

Sum Insured: _____ Excess: _____

(Check Record)

Make of: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lima Sum P/P 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SHD 3846R

Yr Regn:

Dec 2018

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ioniq

C.D.

1580

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

298762

T/Radio:

Insured / Std / NI / NA

Eng/No:

G4LEJU133754

C/No:

KMHLC851CVKU122345

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal

S

mm

R/Bal

S

mm

L/Bal

S

mm

L/Bal

S

mm

D.O.A.

22/04/2021

D.O.L

27/04/2021

Survey held at

Biggest Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SMRT SHF 693

17/12/21

Jurnal P/P 17,144.72 with 10 dgs 2 ren
(CREO \$12,626.19; 42%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 22/12 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

Rep. Form: TP P/P \$17,144.72

REPAIR ESTIMATE

DATE: 23-Apr-21

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD3846R

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~after~~ surface painting
- INSURANCE: Repair damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Description	Qty	List Price	Amount
Front Fender(RH) <i>Demol</i>	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel (RH) <i>HH</i>	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(RH) <i>HH</i>	1	\$ 329.00	\$ 329.00
Front Fender Shield (RH) <i>demol photo src</i>	1	\$ 164.70	\$ 164.70
Frt Door(RH) <i>Demol</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>demol HH</i>	1	\$ 250.00	\$ 250.00
Front Door Regulator (RH) <i>money broken</i>	1	\$ 750.40	\$ 750.40
Front Door Power Motor, RH <i>HH</i>	1	\$ 689.20	\$ 689.20
Front Door Hinge Upper (RH) <i>HH</i>	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (RH) <i>HH</i>	1	\$ 153.70	\$ 153.70
Front Door Check (RH) <i>HH</i>	1	\$ 72.98	\$ 72.98
Front Door Inner Lock (RH) <i>HH</i>	1	\$ 385.60	\$ 385.60
Front Door Mirror ASSY (RH) <i>HH</i>	1	\$ 1,391.70	\$ 1,391.70
Front Door Mirror Holder (RH) <i>HH</i>	1	\$ 175.90	\$ 175.90
Front Door Mirror Lamp (RH) <i>HH</i>	1	\$ 97.10	\$ 97.10
Front Door Trim Board (RH) <i>money broken</i>	1	\$ 796.80	\$ 796.80
Front Door Protector(RH) <i>crack</i>	1	\$ 186.20	\$ 186.20
speaker <i>HH</i>	1	\$ 256.10	\$ 256.10
Rear Door (RH) <i>Demol photo</i>	1	\$ 1,789.90	\$ 1,789.90
Rear Door Rubber(RH) <i>HH</i>	1	\$ 280.00	\$ 280.00
Rear Door Protector(RH) <i>cut/crack</i>	1	\$ 166.20	\$ 166.20
Rocker Panel Outer Garnish <i>demol/cut</i>	1	\$ 715.60	\$ 715.60
Front Windscreen Moulding <i>HH</i>	1	\$ 157.30	\$ 157.30
Front Windscreen Pillar Outer(RH) <i>HH</i>	1	\$ 3,764.90	\$ 3,764.90
Front Wheel Rim (RH) <i>distorted</i>	1	\$ 1,124.20	\$ 1,124.20
Front Wheel Hub Cap and hub assy (RH) <i>cut HH Dam</i>	1	\$ 678.50	\$ 678.50
Front Wheel Hub Cap <i>cut</i>	1	\$ 346.40	\$ 346.40
Front Shock Absorber(Assy)(RH) <i>distorted</i>	1	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (RH) <i>HH</i>	1	\$ 372.50	\$ 372.50
STG Tie Rod <i>HH</i>	1	\$ 125.60	\$ 125.60
STG Tie End <i>HH</i>	1	\$ 94.70	\$ 94.70
Stabilizer Bar <i>HH</i>	1	\$ 326.80	\$ 326.80
Stabilizer Bar Link <i>HH</i>	1	\$ 92.10	\$ 92.10
Front Suspension Lower Arm (RH) <i>distorted</i>	1	\$ 596.80	\$ 596.80
Knuckle Arm (RH) <i>distorted</i>	1	\$ 663.60	\$ 663.60
Rear Bumper <i>HH</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (RH) <i>HH</i>	1	\$ 85.80	\$ 85.80
Rear Bumper Cover Clips <i>HH</i>	1	\$ 22.00	\$ 22.00
Rear Fender(RH) <i>Demol</i>	1	\$ 1,768.30	\$ 1,768.30
Rear Fender SHIELD REAR PIECE (RH) <i>HH</i>	1	\$ 173.60	\$ 173.60
Rear Fender SHIELD Frt Piece (RH) <i>HH</i>	1	\$ 165.50	\$ 165.50
Rear Tyre Rim (RH) <i>distorted</i>	1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hup-Cap (RH) <i>cut/crack</i>	1	\$ 346.40	\$ 346.40

Rear Wheelbearing & Hub assy <i>distorted</i>	1	\$ 554.00	\$ 554.00	✓
Rear Trailing Arm(RH) <i>distorted</i>	1	\$ 265.40	\$ 265.40	✓
Rear Assist (RH) <i>distorted</i>	1	\$ 227.90	\$ 227.90	✓
Rear shock Absorber(RH) <i>distorted</i>	1	\$ 230.50	\$ 230.50	✓
Rear Shock Absorber Mounting (RH) <i>HH</i>	1	\$ 133.10	\$ 133.10	X
Rear Absorber stopper (RH) <i>HH</i>	1	\$ 137.60	\$ 137.60	XX
Rear Absorber Cover (RH) <i>HH</i>	1	\$ 175.60	\$ 175.60	XX
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30	X
Stabilizer Link (RH) <i>HH</i>	1	\$ 147.30	\$ 147.30	X
Rear Upper Arm(RH) <i>distorted</i>	1	\$ 239.50	\$ 239.50	✓
Rear Lower Arm(RH) <i>distorted</i>	1	\$ 393.10	\$ 393.10	✓
Rear Knuckle Arm (RH) <i>distorted</i>	1	\$ 538.10	\$ 538.10	✓
SUB TOTAL			\$ 28,289.54	16266.80
LESS 20%			\$ 5,657.91	13013.44
DISCOUNTED TOTAL			\$ 22,631.63	
Emblem-Blue Drive (RH) <i>Hec</i>	SN 1	\$ 26.60	\$ 26.60	✓
Front Door Comfort Logo (RH) <i>Hec</i>	SN 1	\$ 75.00	\$ 75.00	✓
Rear Door Tel No.Sticker(RH) <i>Hec</i>	SN 1	\$ 10.00	\$ 10.00	✓
Rear Door Comfortdelgro & Apps Sticker(RH) <i>Hec</i>	SN 1	\$ 80.00	\$ 80.00	✓
Front Windscreen Sealant <i>HH Hec HH</i>	SN 1	\$ 46.00	\$ 46.00	X <i>new X</i>
Front ERP Sticker <i>HH</i>	SN 1	\$ 30.00	\$ 30.00	X
Front Tyre(RH) <i>HH</i>	SN 1	\$ 216.00	\$ 216.00	X <i>191-60</i>
Rear Bumper Reverse Sensor <i>HH</i>	SN 1	\$ 180.00	\$ 180.00	XX
Rear Tyre(RH) <i>HH</i>	SN 1	\$ 216.00	\$ 216.00	X
SUB TOTAL			\$ 879.60	
Labour Charge				
Panel Beating	1	\$1,600.00	\$1,600.00	1200/-
Spray Painting Charge	1	\$800.00	\$800.00	700/-
Wiring Charge	1	\$100.00	\$100.00	HH
Tuff Kote	1	\$100.00	\$100.00	40/-
Towing Charge	1	\$80.00	\$80.00	HH
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	HH 80/-
Remove/Refix Fuel Tank	1	\$80.00	\$80.00	HH
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	HH
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$200.00	\$200.00	HH
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$200.00	\$200.00	HH 2500.00
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	150/-
Re-set Frt ABS System	1	\$200.00	\$200.00	150/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	
TOTAL LABOUR			\$4,820.00	
ESTIMATE TOTAL <i>27/04/2021 @ 0945hr</i> <i>HA Andru</i>			\$ 28,331.23	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

4/Sum 10 7 days.
Tyger
2kk Andru

15705.04
supp 1439.68
P/P 17,144.72

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 27-Apr-21

INSURANCE: ~~FCI~~ ^{SMRT}

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD 3846 R

[illegible]

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Customer:	LIM TAN	Date:	4/27/2021 10:20 AM
Company:		VIN	
License NO:	SHD 3846R	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT
HYUNDAI, i30 (GD) All Models, 13-13 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°53'	3°44'	4°44'	5°06'
		Right	5°00'	3°44'	4°44'	4°06'
	Camber	Left	-0°12'	-1°00'	0°00'	0°18'
		Right	-0°54'	-1°00'	0°00'	-2°00'
	Toe	Left	0°15'	-0°06'	0°06'	-1°09'
		Right	-0°09'	-0°06'	0°06'	1°18'
Total		0°06'	-0°12'	0°12'	0°09'	
Rear	Camber	Left	-1°54'	-1°30'	-0°30'	-1°54'
		Right	-3°12'	-1°30'	-0°30'	-2°06'
	Toe	Left	0°06'	0°03'	0°30'	0°03'
		Right	0°51'	0°03'	0°30'	0°30'
		Total	0°57'	0°06'	1°00'	0°33'
	Thrust Angle		-0°22'	99°59'		-0°13'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13°30'	13°18'	14°18'	13°30'
	Right		14°26'	13°18'	14°18'	14°26'
Included Angle	Left		13°18'	99°59'	99°59'	13°48'
	Right		13°32'	99°59'	99°59'	12°26'
Toe Out On Turns	Left		----	99°59'	99°59'	----
	Right		----	99°59'	99°59'	----
Max Turn Inside	Left		----	99°59'	99°59'	----
	Right		----	99°59'	99°59'	----
Toe Curve Change	Left		----	0°00'	199°59'	----
	Right		----	0°00'	199°59'	----
Setback	Front		2mm	2540mm	2540mm	2mm
	Rear		-4mm	2540mm	2540mm	-4mm
Track Width Diff.			-13mm			-13mm
Wheel Base Diff.			6mm			6mm
Front Ride Height	Left		----	2540mm	2540mm	----
	Right		----	2540mm	2540mm	----
Rear Ride Height	Left		----	2540mm	2540mm	----
	Right		----	2540mm	2540mm	----
Frame Angle						----

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHD3846R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Apr 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4LEJU133754
Chassis No.:	KMHC851CVKU122345
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,070.00
Original Registration Date:	11 Dec 2018
First Registration Date:	11 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$12,098.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2026
PARF Rebate Amount:	\$9,073.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$15,521.00
Total Rebate Amount:	\$24,594.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Apr 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/04/2021 15:30 (SGT)
Date of Accident	22/04/2021 21:40 (SGT)
Exact Location of Accident	Collyer Quay, Singapore
Additional Location Information	Outside Ocean Financial Centre towards Nicoll Highway
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3846R
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-92210330
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

DRIVER

Name of Driver	CHUA HUP SOON
NRIC No	SXXXX600H

Date Of Birth	20/08/1963
Occupation	Outdoor
Date Of Driving Pass	10/12/1983
Driving experience	37 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92210330
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 615 BEDOK RESERVOIR ROAD #10-1220
Address complement	-
Postcode	470615
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	SHU QI
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 22 APR 2021 AT ABOUT 2140 HOURS, I WAS TRAVELLING ALONG COLLYER QUAY TOWARDS NICOLL HIGHWAY. SUDDENLY, I FELT AN IMPACT ON MY VEHICLE AND REALISED THAT ANOTHER VEHICLE, SHF69B HAD CRASHED INTO THE RIGHT SIDE OF MY VEHICLE. AFTER THE ACCIDENT HAPPENED, THE OTHER VEHICLE'S DRIVER AND I STEPPED OUT OF OUR VEHICLES. THE OTHER VEHICLE'S DRIVER TOLD ME THAT HE RECEIVED A BOOKING AT OCEAN FINANCIAL CENTRE AND NEEDED TO TURN LEFT INTO THE DRIVEWAY FOR PICK UP.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHF68B
Vehicle Manufacturer	Toyota
Vehicle Model	Prius
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	CHUA HUP SOON
Address	BLK 615 BEDOK RESERVOIR ROAD #10-1220
Address Complement	-
Post Code	470615
Approximate Age Years Old	57
Injuries Sustained	NECK AND BACK PAIN. GIVEN 5 DAYS MC.
Injured person in which vehicle?	SHD3846R
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

WITNESS DETAILS

WITNESS 1

Name	SHU QI
Phone	(Phone) +65-96429218
Email	-



SINGAPORE POLICE FORCE



T/20210423/7006

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20210423/7006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/04/2021 10:14		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: CHUA HUP SOON			Address: 615 BEDOK RESERVOIR ROAD #10-1220 SINGAPORE 470615		
ID Type / ID No.: NRIC NO / S1583600H			Contact No.: Home/Office: Mobile: 92210330		
Nationality: SINGAPORE CITIZEN			Email: chuahupsoon@gmail.com		
Sex: Male	Age: 57	Date of Birth: 20/08/1963	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/04/2021 21:40	Type of Location: Straight Road
Location: COLLYER QUAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SHD3846R	Car	HYUNDAI	IONIC	Blue	Seriously Damaged	1
SHF69B	Car	TOYOTA	PRIUS	Maroon	Seriously Damaged	0



SINGAPORE POLICE FORCE



T/20210423/7006

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20210423/7006

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHUA HUP SOON	ID No.	S1583600H
Related Vehicle	SHD3846R (Car)	Contact No.	92210330
Hospital/Clinic	OUR FAMILY PHYSICIAN CLINIC & SURGERY	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	23/04/2021	Date	23/04/2021
No. of Days granted Medical Leave	05	Degree of	Slight

Brief Details.

On 22/4/2021 at about 2140 Hrs,i was driving my taxi SHD3846R along Collyer Quay towards Esplanade Dr with 1 passenger onboard.I was traveling straight on the extreme Left Lane of 4 Lane Road at the point of time.Out of sudden,i felt a great impact from my right side portion and the impact surged my body to the left and pull back by the safety belt.After the accident i alight my taxi and realized that a taxi SHF69B encroach into my Lane from the right and cause damage and dented to my taxi right side portion.The said driver admitted his fault as he get a booking and did not check his blind spot and recklessly cut into my Lane.I request to exchange particular but the driver refuse to give,so i take some scene photo and leave the scene.My neck and back was in pain due to the impact of the accident and today when i wakes up the pain more worse so i consult doctor and was given 5 days MC from 23/4/2021 to 27/4/2021.



**SINGAPORE
POLICE FORCE**



T/20210423/7006

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20210423/7006

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
TAN JEOK LENG
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
23/04/2021 10:14

Classification Of Case:

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Agnes Ho
NRIC/FIN No.:

CS Scanned with CamScanner

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22 Apr 2021 at about 2140 hours, I was travelling along Collyer Quay towards Nicoll Highway. Suddenly, I felt an impact on my vehicle and realised that another vehicle, SHF69B, had crashed into the right side of my vehicle. After the accident happened, the other vehicle's driver and I stepped out of our vehicles. The other vehicle's driver told me that he received a barking at Ocean Financial Centre and needed to turn left into the driveway for pick up.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 10/11/21 22/4/21

Reporting Centre Personnel's Signature
Name: Agnes Ho
NRIC/FIN No.:



Scanned with CamScanner