



Service Requests

Messages

Claims



Service Request Details

Claim	S1M03770
Reference	CS3/ASM21005164/Uvce2 
Loss Date	3 April 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	23 Apr 2021 2:33:00 PM
Request Date	26 April 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	GZ609A
Vehicle	
Registration #	
Make	TPVD Toyota
Model	Hiace

Service Address

’ ’ ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

YU Dominic Yishan

dominic.yuys@axa.com.sg

Additional Instructions

Messages2InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
ASM_LKKInvoice_AC2103332.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	12 May 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	12 May 2021
 LKK RES PHOTOS.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 May 2021
 IA (PRS).pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 May 2021
 LKKPhotosIn4.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 May 2021
 SHA2826X INDS GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	23 April 2021
 EMAIL FROM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	23 April 2021
 GZ609A TP GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	23 April 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 SJ042144000E-SHA2826X.pdf.pdf	Reports & Statement	Accident statement	ILHAM Luqman Hakim	5 April 2021