NOT Authornal
NO

				CURVENADIC
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)		-1.	4 2/22
1	Tailgate		Bady 20 3250.00	2/50.70
1	Tailgate <del>edge</del> weatherstrip		141 375.20	
1	Tailgate centre chrome garnish		but (cre 289.50	
1	Tailgate inner lock (top)		Should 275.20	
1	Tailgate inner lock (top) cover		NF 122.00	
1	Tailgate lock catch (lower)		مر 142.60	
2	Tailgate damper @322.70		11 645.4	o X
2	Tailgate hinges @ 98.50		A 1 197.0	· ·
1	Tailgate Inner trim board		Delson 250.00	/ 2
1		REFIX	77 0.00	
1	Rear wiper arm	REFIX	11 0.00	
1	Rear wiper blade	REFIX		0 7
1	Rear wiper motor	REFIX		
2	Rear number plate lamp @58.00	KELIX	116.0	
1			De 1428.0	0000
	Rear bumper Rear bumper beam		NF 232.0	
1	The state of the s		14 56.0	1 *
2	Rear bumper side stopper @28.00	30×2560		2005
4	Rear bumper lover brockets @ 49.20	304 6 - 00	N7 328.0	1-111
1	Rear bumper step garnish			1'
2	Rear RHS & LHS Corner panel @389.50		779.0	
2	RHS & LHS Taillamp @795.80	DEDAID	1591.6	
1	Rear floor panel	REPAIR	R 0.0	
1	Rear end panel (inner)		1 982.0 1 1 1 9652	. //.
1	Rear end panel (outer)		3,3.2	
1	Rear end panel top garnish		7wi 328.0	The second second
1	Rear exhaust silencer assy		11 792.0	
2	Rear exhaust silencer assy mountings		7 96.0	
			12437.5	
		less	25% 3109.3	_
			9328.1	3
	SPECIAL NETT ITEMS		100	
1	Toyota Badge		1	0 45
1	Tailgate ctr Chrome "EMERGENCY DOOR" stic	ker		0 20
1	Tailgate ctr Chrome "PULL TO OPEN" sticker			0 20
1	Tailgate HIACE emblem			030
1	Tailgate GL emblem			0 30
1	Spare tyre holder		IM 150.0	
1	Spare tyre		11 280.0	0 ×
1	Reverse camera		11 380.0	
1	Rear Windscreen Sealant			0 40
1	Rear end panel sealant		nee 100.0	020
1	Rear Licence Plate w/holder			0 ×

**TOYOTA HIACE VEHICLE NO. PC 7027Y** 

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1400.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	600
3	To remove, refix wiring system at accident damaged areas and check for proper function	250.00	20
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	250.00	So
5	To remove and refix rear windscreen	140.00	100
6	To remove and replace reverse camera and test for proper function	100.00	40
7	To remove and replace rear exhaust silencer assy and realign to fit and check for system function	250.00 1~	X
8	To perform anti-rust treatment on affected areas	180.00	60
	Labour Total :	3570.00	
	TOTAL (PARTS & LABOUR):	14345.13	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "V-ithout Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

P-370050 P-370050 S.N-235.00 L-1700.00 20 20 4108

SA1E214O0001 / Abwin Service Pte Ltd ENTRY DATE & TIME: 24/04/2021 12:06 (SGT) SUBMITTED BY: Gerine Cheng VERSION: 1 (24/04/2021 12:06 (SGT))



# SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

. Please report correctly the details of the accident to speed up the claims process

This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

24/04/2021 12:06 (SGT) 23/04/2021 17:25 (SGT) PIE, Singapore PIE TOWARDS CHANGI Singapore

# DETAILS OF OWN VEHICLE

Vehicle Registration Number

PC7027Y

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No

JAPS TRANS PTE LTD 2XXXXX027C SPJULIUSAJ@GMAIL.COM (Phone) +65-94515319 (Home) +65-94515319

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category

Transmission

CC

Toyota Hiace

Employment

No - Claiming third party

Bus Auto 2754

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number NTUC Income Insurance Co-operative Ltd Comprehensive

No

5100195092-02

DRIVER

Name of Driver NRIC No

SAVARIMUTHU PETER JULIAS@PETER JULIUS SXXXX530B

Date Of Birth \*
Occupation

Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number Email Address

Address
Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

PASSENGER 1

Name

Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Was there any audio recorded?

Yes

17/04/1967

10/05/2001

19 YEARS AND 11 MONTHS

SPJULIUSAJ@GMAIL.COM

(Phone) +65-94515319

**BLK 44 SIMS DRIVE** 

Collision - Head to Rear

Outdoor

#04-151

380044

**Employee** 

No

No

Clear

Dry

No

Yes

Yes

2

No

Female

No

No

**GABRIEL ANNACIA** 

No

2

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category

PD1033M

-

\_

Commercial vehicle

Commercial ve

Accident report SA1E214O0001

Page 2 of 18

LIM TIEN GUEY Name of Driver Passport No/FIN GXXXX879M Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

# INJURED PERSONS DETAILS

### INJURED 1

SAVARIMUTHU PETER JULIAS@PETER JULIUS Name of injured person

Address

Address Complement

Post Code

Approximate Age Years Old

Injuries Sustained MC 2 DAYS Injured person in which vehicle? PC7027Y

Were seat belts worn? Yes No

Was this injured conveyed to hospital by ambulance?

	nstances of the Accident
on the	Stated date and time, I was driving vehicle A along
	occards Changi. As there was slow traffic on the
	v
highway,	and I was driving at a speed of 30-40 km/hr,
0	
vehicle i	nfront of me made a sudden broke, as I was braking
enddenl	y vehicle B collided onto my vehicle.
GACTOLLI	y venice B conided office ing venice.
***************************************	
***************************************	
***************************************	
1888##################################	
-	
***************************************	
<del></del>	
and the second s	
WINDOWS PROPERTY OF THE PROPER	
***************************************	

Declaration

JAPS TRANS PTE LTD We declate the foresting particulars are true in every respect UEN: 201510027C 44 SIMS DRIVE, 04-151 SINGAPORE 380044 Tel: +65 6698 7226



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Winessed by Reporting Centre Personnel

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmost be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or widtholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing handling and/or dealing with my claims

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collectuse, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

JAPS TRANS PTE. LTD.

UEN: 201510027C 44 SIMS DRIVE, 04-151 SINGAPORE 380044 Tel: +65 6698 7226

Busi

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## Sketch Plan

p : 7070271

