

Chino (P/P) 74

COMFORTDELGRO ENGINEERING PTE LTD

Date: 31.03.2021

Time: 10:57:49

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305461327
 REGN NO : SHD4264M
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 23.01.2020
 DATE/TIME IN : 31.03.2021 10:05
 ACCIDENT DATE : 27.03.2021

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
 Date:

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
PART REQUISITION					
0001 04-01-0104-2282-G COVER-RR BUMPER#	1		459.40	20.00	367.52
0002 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C	1		451.25	20.00	361.00
0003 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L		22.00	20.00	17.60
0004 04-01-0104-1150-A PROTECTOR MAT	1		50.00	2.00	50.00
0005 04-01-0104-2226-G LAMP ASSY-LICENSE PLATE	1		85.30	20.00	68.24
0006 04-01-0104-2544-G CAP-RR HOOK	1		98.80	20.00	79.04
0007 FNPS NUMBER PLATE FRONT	1 N		25.00	2.00	25.00
0008 09-01-0104-2133-G ANTENNA ASSY-SMARTKEY	1		40.50	20.00	32.40

1087.65

870.12

SN-75

SUB-TOTAL : 1,000.80

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30 630

Tanpin 92475749 waste.
 31/3/3 @ 5pm
 P/P Resurvey before paint
 2 days
 Tanpin & Chandra

870.12
 75
 630

\$ 1575.12
 2 days

JUMANI