

Your Ref: CLE.atv.INS.T140.103795.17/SN

Date: 08th June 2021

Our Ref: CS1/LAW21005177/Atf3e2

M/s Vision Law LLC

133 New Bridge Road #18-01/02

Chinatown Point

Singapore 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GR 2442S**INSURED VEHICLE: SGP 6930J****ACCIDENT DATE: 21/07/2017**

We thank you for your instruction on 26/04/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GR 2442S from M/s Constant Appraiser Services.
- b) Survey report by Formteam Adjusters Pte Ltd with colour photographs.
- c) Final Repair Bill of GR 2442S from M/s Twincar Automotive Pte Ltd.
- d) Singapore Accident Statement of Vehicles GR 2442S and SGP 6930J.
- e) Colour damaged vehicle photographs of GR 2442S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GR 2442S
Make & Model	: Toyota Hiace Diesel
Chassis Number	: LH1620006807
Year of Registration	: 1999
Engine Capacity	: 2986 cc

- 2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.