

Our Job Ref No : 305465732  
Date : 20/04/21

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK  
Attn : NAZ  
Vehicle Reg No. : SH 6285M

Fax :

24/04/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: NTUC SLB5970P

2. The finalized amount shall be:


(a) Spare Parts after List discount	<u>\$806.04</u>
(b) Labour Charges	<u>\$825.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<u>\$1,631.64</u>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less:	
<b>Final Lumpsum Repair cost</b>	


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : CHIANG  
Tel : 62148314  
Fax : 65468156

Signature :   
Name : NAZ LKK  
Date : 31/5/2021

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305465732  
REGN NO : SH 6285M  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 22.10.2019  
DATE/TIME IN : 26.04.2021 14:00  
ACCIDENT DATE : 24.04.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0104-0578-G	COVER-FR BUMPER#	1	430.90	20.00	344.72
0002 04-01-0104-2687-G	MOULDING-FRONT BUMPER CTR	1	368.50	20.00	294.80
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004 04-01-0104-2685-G	MOULDING-FRONT BUMPER LH	1	186.90	20.00	149.52

SUB-TOTAL : 806.64

## JOB NATURE

0000 PB	PANEL BEATING	450.00
0001 SP	SPRAYPAINT CHARGE	375.00

SUB-TOTAL : 825.00

TOTAL : 1,631.64

MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

**COMFORT DELGRO  
ENGINEERING**

VEHICLE 1 SH6285M

SH6285M

TYPE OF C: TP

TP

**NTUC**

**NTUC**

SURVEY B': LKK/NAZ/

LKK/NAZ/

**305465732**

**305465732**

DATE : 24/04/2021

**24/04/2021**

### SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 29.04.2021

Time: 13:48:25

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305465732  
REGN NO : SH 6285M  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 22.10.2019  
DATE/TIME IN : 26.04.2021 14:00  
ACCIDENT DATE : 24.04.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0104-0578-G	COVER-FR BUMPER#	1	430.90	20.00	344.72
0002 04-01-0104-2687-G	MOULDING-FRONT BUMPER CTR	1	368.50	20.00	294.80
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004 04-01-0104-2685-G	MOULDING-FRONT BUMPER LH	1	186.90	20.00	149.52

SUB-TOTAL : 806.64

## JOB NATURE

0000 PB	PANEL BEATING	450.00
0001 SP	SPRAYPAINT CHARGE	375.00

SUB-TOTAL : 825.00

TOTAL : 1,631.64

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :



**COMFORT DELGRO  
ENGINEERING**

VEHICLE 1 SH6285M

NTUC

**305465732**

TYPE OF C: TP

SURVEY B': LKK/NAZ/

DATE 24/04/2021

### SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]