

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305465516  
Date : 29/04/21

## FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SH 8260X

Date of Accident : 24/04/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SJL564H  
###
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$1,590.76
  - (b) Labour Charges \$2,005.00
  - Total for Part-By-Part Repair Cost** \$3,595.76
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : [Signature]  
Name : JUMANI  
Tel : 62148315  
Fax : 65468156

Signature: [Signature]  
Name : NAZ LKK  
Date : 3/5/2021

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	--	N		
3. Survey Fees	--	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305465516  
REGN NO : SH 8260X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 22.10.2019  
DATE/TIME IN : 24.04.2021 17:15  
ACCIDENT DATE : 24.04.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0104-0593-G	PANEL ASSY-FRONT DOOR LH#	1	1,797.20	20.00	1,437.76
0002 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	10.00	67.50
0003 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00
0004 28-01-0302-2017-A	FUEL TANK LID (PETROL ONL	1 N	15.00	10.00	13.50

SUB-TOTAL : 1,590.76

## JOB NATURE

0000 PB	PANEL BEATING	1050.00
0001 SP	SPRAYPAINT CHARGE	875.00
0002 L	TRANSFER DOOR PART	50.00
0003 L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 2,005.00

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 29.04.2021

Time: 09:38:56

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305465516  
REGN NO : SH 8260X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 22.10.2019  
DATE/TIME IN : 24.04.2021 17:1  
ACCIDENT DATE : 24.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,595.76

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
PATROL STICKER	1	\$15.00	NETT / NEC
CHECK ITEM			
LABOUR			
TOTAL:		\$15.00	JUMANI

# PORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH8260X  
 Make : HYUNDAI  
 Model : IONIQ

DOA: 24.4.21

Date: 26.04.21  
 Insurance: NTUC  
 MVA: JUMANI

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
1	REAR DOOR ASSY LH			\$1,789.90
1	FRT DOOR ASSY LH			\$1,797.20
1	ROCKER PANEL LH			\$290.00
10	REAR BUMPER CLIPS			\$22.00
SUB TOTAL				\$4,358.50
LESS 20%				\$871.70
DISCOUNTED TOTAL				\$3,486.80
	FRT DOOR COMFORTDELGRO LOGO			\$75.00
	REAR DOOR APPS LOGO			\$80.00
				\$155.00
Labour Charge				\$1,100.00
PANEL BEATING				\$1,000.00
SPRAYPAINT				\$80.00
REMOVE/REFIX REVERSE SENSOR				\$240.00
TRANSFER DOOR PARTS				
TOTAL LABOUR				\$2,420.00
ESTIMATE TOTAL				\$6,061.80
				6076.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be

NA2 LKK  
 27/4/2021 1510  
 P/P  
 3 DAYS  
 BY PAINT & PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: