

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Piaggio GILERA RUNNER ST 200 (FBK7686T)
Date of Loss	15 April 2021
Time of Loss	15:30
Loss Description	SHD3154D (INSD) TURN RIGHT TO MINOR ROAD HIT FBK7686T GOING STRAIGHT (TP)
Comment	

Workshop Details

Total Rebate Amount	<div>0</div>
Nett Loss Amount	-\$471.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<div>20</div>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details


Vehicle Registration#	FBK7686T	Purchase Date	<div>DD/MM/YYYY</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>16/12/2013</div> <div></div>
Mileage	<div></div>	Age of Vehicle	7

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2012</div>



Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
----------	------------------	-------------------------

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Piaggio	<input type="text" value="PIAGGIO"/>
Model	GILERA RUNNER ST 200	<input type="text" value="GILERA RUNNER ST"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="ZAPM464010000704"/>
Engine No		<input type="text" value="M464M0010380"/>
Engine Capacity		<input type="text" value="198"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	MUHAMMAD NUR HADI BIN MOHD GHAZALI	<input type="text" value=""/>
Date of Birth	31 July 1997	<input type="text" value="DD/MM/YYYY"/> 
Age	23	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Issue Date		<input type="text" value="DD/MM/YY"/> 
License Expiration Date		<input type="text" value="DD/MM/YY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	S9725327G	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

28/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

120/70-14

Front left side

PIRELLI5mm

Front right side

Spare wheel

Rear Tyre Size

140/60-13

Rear left side

PIRELLI5mm

Rear right side



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages

Claims























Assessment Details


General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio **Parts & Labour** Miscellaneous Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PA
	0	1		FRONT FENDER	Broken	0	152	No	0	10	0	0	136.8	Re
	0	1		FRONT FORK ASSY	Twisted	0	820	No	0	10	0	0	738	Re
	0	1		FRONT RIM	Damaged	0	550	No	0	10	0	0	495	Re
	0	1		FRONT RIM SHAFT	Bent	0	50	No	0	10	0	0	45	Re
	0	1		FRONT BRAKE DISC	Damaged	0	190	No	0	10	0	0	171	Re
	0	1		METER ASSY	Cracked	0	680	No	0	10	0	0	612	Re
	0	1		HEADLAMP	Broken	0	320	No	0	10	0	0	288	Re

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PA
	0	1		SET SIDE MIRROR	Damaged	0	180	No	0	10	0	0	162	Re
	0	1		HANDLE BAR	Bent	0	182	No	0	10	0	0	163.8	Re
	0	1		HANDLE BAR BALANCER N/S	Cut	0	40	No	0	10	0	0	36	Re
	0	1		SET HAND GRIP	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		BRAKE LEVER	Cut	0	50	No	0	10	0	0	45	Re
	0	1		SET FRONT SIGNALS	Broken	0	180	No	0	10	0	0	162	Re
	0	1		FRONT COWLING	Broken	0	380	No	0	10	0	0	342	Re
	0	1		SET FRONT COWLING SIDE COVER	Broken	0	500	No	0	10	0	0	450	Re
	0	1		LOWER BELLY PANEL	Damaged	0	320	No	0	10	0	0	288	Re
	0	1		HANDLE-BAR INNER COVER	Damaged	0	250	No	0	10	0	0	225	Re

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC1 (PA
	0	1		TOP COVER	Cracked	0	280	No	0	10	0	0	252	Re
	0	1		FRONT INNER COVER - L/H	Cracked	0	320	No	0	10	0	0	288	Re
	0	1		TOP FOOTSTEP PANEL - L/H	Cracked	0	180	No	0	10	0	0	162	Re
	0	1		BOTTOM FOOTSTEP PANEL - L/H	Damaged	0	160	No	0	10	0	0	144	Re
	0	1		REAR FAIRING - L/H	Cut	0	450	No	0	10	0	0	405	Re
	0	1		SET REAR SIGNAL	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		REAR HANDLE	Cut	0	140	No	0	10	0	0	126	Re
	0	1		DROVE BELT COVER	Cut	0	180	No	0	10	0	0	162	Re
	0	1		MAIN STAND	Cut	0	165	No	0	10	0	0	148.5	Re
	0	1		SIDE STAND	Repair	0	0	No	0	0	0	0	0	De

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PA
	0	1		RADIATOR	Damaged	0	520	No	0	10	0	0	468	Re











Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO PROVIDE TOWING	0	35	0	0	Reviewing		
	0		TO CHECK ELECTRICAL AND HEADLAMP FOCUSING	0	0	0	0	Deny		
	0		TO REPAIR BODY FRAME	0	0	0	0	Deny		
	0		TO PROVIDE LABOUR	0	400	0	0	Reviewing		
	0		TO RESPRAY PAINTING	0	500	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition





Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 6 DAYS	Reviewing	0	0		
	0	1 SET NUMBER PLATE	Reviewing	0	10	DAMAGED	
	0	FORK OILS (2PCS)	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FORK OIL SEALS (2PCS)	Deny	0	0	NOT NECESSARY	
	0	1 SET STEERING CONE BEARING	Reviewing	0	60	NECESSARY	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$7,520.10
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$6,515.10
Labour	\$0.00	\$935.00
Miscellaneous	\$0.00	\$70.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

3500





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$3,500.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$3,500.00

Submit for Review