

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SHA 2021B  
 at Workshop m/s ComfortDelGro Engineering  
 of \_\_\_\_\_  
 Insured: YP 7373Y  
 Policy No. \_\_\_\_\_  
 Claims No. MT/1129955-002  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

X

|     |     |
|-----|-----|
| N/S | O/S |
| LHS | RHS |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 2021B Yr Regn: 30 MAY 2017  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: TOYOTA PRIUS C.C. 1,785

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 569,090 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU003557326

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / tyre brands  
 TOYO / YOKO or WESTLAKE

Front Rear  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 27/4/2021 D.O.I. 28/4/2021

Survey held at CDGE LOYANG  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
FRONT OFFSIDE NEARSIDE

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time      | Action / Instruction                                         |
|------------------|--------------------------------------------------------------|
| <u>31/5/2021</u> | <u>FINALIZED LUMP SUM REPAIR \$ 1,750.00 / 2 REPAIR DAYS</u> |
|                  | <u>(RED \$2249.36; 56%)</u>                                  |
|                  |                                                              |
|                  |                                                              |
|                  |                                                              |
|                  |                                                              |
|                  |                                                              |
|                  |                                                              |
|                  |                                                              |
|                  |                                                              |

Date/Time, File Pass to? ☐ : Preli. Report

1) 4/5 TYPIST ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format : TP

Lump Sum / L.B. : (\$ 1750 )

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Date/Time: 28.04.2021 10:46

Page : 1

Team: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order:

JC NO.:305466064

Customer: COMFORT TRANSPORTATION PTE LTD  
Customer NO. 7010045  
Address: 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)

Amount CARD NO.


|                                          |                                      |
|------------------------------------------|--------------------------------------|
| REGN NO.:<br><b>SHA2021B</b>             | MILEAGE                              |
| MAKE:<br><b>TOYOTA</b>                   | FUEL<br>E.....1/2.....F              |
| MODEL<br><b>PRIUS HYBRID(G4)27</b>       | DATE/TIME IN<br><b>04.2021 16:10</b> |
| YR OF MANU.<br><b>30.05.2017</b>         | TARGET DATE                          |
| CHASSIS CODE<br><b>JTDKB3FU003557326</b> | COMPLETION DATE/TIME:                |

JOB DESCRIPTION

Accident Date: 27.04.2021

Incident Nature: 3P 27.4.2021

Job No LABOR CODE DESCRIPTION



Worked & Passed Out By:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Work Order Slip

Exit Pass

Vehicle No.: **SHA2021B**

JU NTUC LKK

Vehicle No.:

**SHA2021B**

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard