

ASS. REC. BY: Steve

CS3/AIG 21005260/LEV3

ASSIGNMENT

P.R.S.

From: _____ Date: _____

Estimated Cost: _____

OD / TH / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLW 8996K

Policy No. 1800023547


Claims No. 7066901141SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

SIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Cum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKE 7379E Yr Regn: 2016/19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit c.c. 1496Colour: White A/C: Insured / Std / NI / NSp. Reading: 30552 T/Radio: Insured / Std / NI / N

Eng/No: _____

C/No: GB 71989-187Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orMod: Nil / 8/Rim / STD A/Rim orTyre Size: F: 205/50R16R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 24/4/21D.O.I. 29/4/21Survey held at PER TING AutoDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop orFIRN

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Mr. 97K

5/5/21 Submit DAR

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Date/Time, File Return to?

5/5/21-Typist

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Inve (\$ _____)☐ : Wash and (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Phone

Others

TOTAL

DAR

Date/Time, File, Pass to?

SINGAPORE ACCIDENT STATEMENT

TANT NOTICE

se report correctly the details of the accident to speed up the claims process.

Form must be completed by the Policyholder and/or the Authorised Driver

information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate

ability

issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

false reporting may be referred to the Police for investigation.

report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

it copies of this report will, for a fee, be made available upon application by interested parties.

ie lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/04/2021 11:46 (SGT)
Date of Accident	24/04/2021 10:30 (SGT)
Location of Accident	Sembawang Ave, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE7379E
-----------------------------	----------

INSURED/POLICYHOLDER

Company?	No
Name of Registered Owner	LEE PUI CHIA
No	SXXXX276A
Full Address	PUICHIA11@GMAIL.COM
Home Phone No	(Phone) +65-94358594
Mobile Phone No	+65-94358594

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Freed
Registration	-
Intended purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
Year	1496

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Policy Number	No
Policy Number	GA477166
Effective Date	20/06/2020 - 19/06/2021

SIGNATURE

Signature of Driver	LEE PUI CHIA
Signature No	SXXXX276A

Pass
Age
Sex
Number
Address
Occupation
Is the policyholder?
Relationship of the Driver with the Insured
Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

04/06/1979
Indoor
14/01/2002
19 YEARS AND 3 MONTHS
Male
(Phone) +65-94358594
+65-94358594
PUICHIA11@GMAIL.COM
180 CANBERRA DR
#08-23
767952
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

How did the Accident occur?
Weather Conditions
Road Surface

Collision - Cross Junction
DRIZZLING
Wet

PERSONS INVOLVED

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has a driver been approached by unknown person(s)
Is anyone offering accident claims assistance?

No
2
No
-
Yes
3
No
No

DRIVER 1

Name
Gender

LEE HONG WEN
Male

DRIVER 2

Name
Gender

LEE CHENG XI
Male

ACTIONS OF POLICE

Has the accident been reported to the police?
Has a notice of intended Prosecution been given?
Against whom?

No
No
-

PLACES OF ACCIDENT

REFERENCE TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are identification photos available for attachment?
Are any video captured by Car Camera?
Are any audio recorded?

Yes
Yes
No

DETAILS OF OTHER VEHICLE PROPERTY

Registration Number
Manufacturer

SLW8996K
-

-
-
-
Private car
GOH POH GEOK
SXXXX489Z
(Phone) +65-83688378
-
-
-
-
-
-

er
plement
Company Name
Damage
property damaged in accident
passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 26th Apr. 2021

9:15 am

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date of accident: 24th Apr 2021 Time: 10:30am Location: Sembawang Avenue
 My Vehicle A: SKE 7374G Vehicle B: SLW 8996E Vehicle C: -
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24th April 2021 around 10.30am, it was drizzling and I was driving towards Sembawang Avenue on straight. The traffic light was green in favor for me to drive through. Suddenly vehicle B (SLW 8996E) turned right and I couldn't stop in time and collide with vehicle B. Photos & videos are as attached.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
 Email address :
 & myself :
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 26th Apr 2021
 9:15 am

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre/Insurer's Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY



POLICYHOLDER ACKNOWLEDGEMENT FORM

Date: 9/6/14

To: Owner of Vehicle Number: JKC2345

The following has been advised to you via your workshop: AH LIM MOTOR COMPANY through their staff, Ernest Che, Mr. Hong, Wai-lie. Please tick the applicable box if you had been advised on any of the following.


- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ If fire damage and you claim under your own insurance, any applicable excess will be waived. However, there will be no recovery prospect and NCD will be affected.
- ☐ If fire damage and you are claiming against the Third Party, your NCD will not be affected. However, the recovery is not guaranteed, and AXA will not be held responsible.
- ☐ You have agreed to let AXA assign a workshop for your vehicle repairs. In the process, your vehicle might be towed out to another workshop assigned by AXA. In return, you will get:
- ☐ \$200 off on your Basic Own Damage Excess or
 - ☐ \$200 as a benefit if your policy has \$0 excess and no Loss of Use benefit or
 - ☐ Additional \$200 on top of existing Loss of Use Benefit if your policy has \$0 excess and existing Loss of Use benefit
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to import it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☐ For vehicles below three (3) years old or under warranty with a local distributor, your insurance company will use only original parts to repair your vehicle.
- ☐ For vehicles above three (3) years old and no longer under warranty with a local distributor, your insurance company will be carrying out repairs where any damaged part that can be repaired will be repaired and any part that needs to be replaced will be replaced using any combination of original parts and/or original equipment manufacturer (OEM) parts and/or second-hand parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

☒ Others Claim Third Party @ Own Workshop.

Signed and acknowledged by:

[Signature]
Name and signature of policyholder/authorized driver* and company stamp (where applicable)
*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured vehicle.

Wg [Signature] Name and signature of workshop personnel including company stamp



(1)Front (2)Rear (3)Frontal (4)Rear (5)Frontal (6)Rear
 (7)Frontal (8)Rear (9)Frontal (10)Rear (11)Frontal (12)Rear
 (13)Frontal (14)Rear (15)Frontal (16)Rear (17)Frontal (18)Rear

MOTOR CAR (100)

AC/100/100

Aug 1995

(1)Front (2)Rear (3)Frontal (4)Rear (5)Frontal (6)Rear
 (7)Frontal (8)Rear (9)Frontal (10)Rear (11)Frontal (12)Rear
 (13)Frontal (14)Rear (15)Frontal (16)Rear (17)Frontal (18)Rear

Vehicle No.

SKE 7379E

Front Portion

NAC	IPC	Item	COPI	AC	Qty
1001	991836	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR	✓	
1005	992341	Frt Bumper Clips	IXC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	BR	✓	
1008	991433	Frt Bumper Reinforcement	BT	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991463	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Hom			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990705	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990123	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990829	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991711	Front Exhaust Pipe			
1067	990219	Catalytic			
1068	990234	Battery Cover			

NAC	IPC	Item	COPI	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991834	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992093	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991890	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

4 repair dgs