

ASS. REC. BY:

REF:

AIG/ 21005267/kg

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLX 7204P Yr Regn: 04, 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Vios E c.c. 1496Colour: M. Red A/C: Insured / Std / NI / NASp. Reading: 121231 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 2B 23 F 340111 8304Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 23/4/21 D.O.I. 17/5/2021

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/7 21:00 @ 2260d Car Insured

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Add Fee: ☐ : Site Insp (\$ _____)

Transportation: _____

☐ : Interview (\$ _____)

S - RS - SI

☐ : Tech Invs (\$ _____)

Furnish

☐ : Weekend (\$ _____)

Others

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLX7204P
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 25/04/2021
TP Veh Reg No: SJR5325S

Estimate No: ES2190454/YISHUN
Date: 15 May 2021
Policy No: 5099395968-03
Veh Reg No: SLX7204P
Make/Model: TOYOTA TOYOTA VIOS E(AUTO)
Chassis No: MR2B23F3401118304
Engine No: 2NR5210856
Reg. Date: 09/04/2018

Not Withheld

11 Sup & 2600L

Mercury After Paint

Today

Estimate Repair Cost to Vehicle No :SLX7204P

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	489.10	1 PC	489.10	✓
2 REAR BUMPER SIDE RETAINER	133.90	2 PCS	267.80	✓
3 REAR BUMPER CLIP	3.50	6 PCS	21.00	✓
4 REAR BOOT	611.90	1 PC	611.90	✓
5 REAR BOOT LOGO	50.20	1 PC	50.20	✓
6 REAR BOOT EMBLEM - VIOS	49.50	1 PC	49.50	✓
7 REAR BOOT EMBLEM - E	39.80	1 PC	39.80	✓
8 REAR BOOT INNER LOCK	360.42	1 PC	360.42	✓
9 REAR BOOT INNER RUBBER	166.40	1 PC	166.40	X
10 REAR PANEL	620.00	1 PC	620.00	✓
			2,676.12	
		Less 25%	669.03	2,007.09
Special Net				
11 REVERSE SENSOR	200.00	1 PC	200.00	✓
			200.00	200.00
Labour				
12 TO PANEL BEATING	650.00	1 LA	650.00	600L
13 TO PUTTY AND RESPRAY ON REAR BOOT, REAR PANEL, REAR BUMPER	750.00	1 LA	750.00	660L
			1,400.00	1,400.00
			Total	S\$ 3,607.09
			Add GST @ 7%	252.50
			Total Amount Payable	S\$ 3,859.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

SLX7204P
TP/MG

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

698B

Vehicle Details

Vehicle No.:

SLX7204P

Vehicle to be Exported:

No

Intended Deregistration Date:

26 Apr 2021

Vehicle Make:

TOYOTA

Vehicle Model:

VIOS E (AUTO)

Primary Colour:

Red

Manufacturing Year:

2018

Engine No.:

2NR5210856

Chassis No.:

MR2B23F3401118304

Maximum Power Output:

79.0 kW (105 bhp)

Open Market Value:

\$13,707.00

Original Registration Date:

09 Apr 2018

First Registration Date:

09 Apr 2018

Transfer Count:

0

Actual ARF Paid:

\$13,707.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

08 Apr 2028

PARF Rebate Amount:

\$10,280.00

Intended COE Rebate Details

COE Expiry Date:

08 Apr 2028

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$38,000.00

COE Rebate Amount:

\$26,418.00

Total Rebate Amount:

\$36,698.00

The information contained herein is correct as at 26 Apr 2021

OK