

Our Job Ref No : 305466250  
Date : 30/04/21

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :


Attn : NAZ


Vehicle Reg No. : SHA9195L

Date of Accident : 28/04/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SMY2774B  
###
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$2,200.00  
**Final Lumpsum Repair cost** \_\_\_\_\_
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 62148315  
Fax : 65468156

Signature :   
Name : NAZ LKK  
Date : 3/5/2021

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	--	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

TP INSURER:  
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Jumani

*(Signature)*

Singapore

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/04/2021
Vehicle Reg. No.:	SHA9195L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 GDI (A)	Vehicle Reg. Date:	11/08/2016
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4FDGU662594	Chassis No:	KMHLB41UMGU092600
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

### COST OF CLAIMS

	Amount
Parts	2,572.00
Miscellaneous Items	11.00
Labour	650.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,233.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>226.31</b>
<b>Nett Amount (S\$)</b>	<b>3,459.31</b>

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference**

**Part Source:** (Last Synchronised: 29 Apr 2021)

**Parts:** N/A HYUNDAI I40 1.7 GDi (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA9195L/29/04/2021 08:59

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	20.00	0.00	*1,052.20 FL /DEF
2	10		*FRT BUMPER CLIPS	20.00	0.00	*22.00 FL /NEC
3	1		*FRT BUMPER SPONGE	20.00	0.00	*379.20 FL ?XSVL
4	1		*RADIATOR GRILLE	20.00	0.00	*1,480.00 FL /CRK
5	1		*RADIATOR GRILLE EMBLEM	20.00	0.00	*129.50 FL /NEC
6	1		*FRT BUMPER SIDE BRACKET LH	20.00	0.00	*44.80 FL ?XSVL
7	1		*FRT BUMPER SIDE BRACKET RH	20.00	0.00	*44.80 FL ?XSVL
8	1		*FRT NUMBER PLATE WITH CASING	0.00	0.00	*50.00 F /SCR
						CRK
<b>Sub Total (S\$)</b>						<b>3,202.50</b>
<b>- List Item Discount on L Items (S\$)</b>						<b>630.50</b>
<b>Total Parts (S\$)</b>						<b>2,572.00</b>

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA9195L/29/04/2021 08:59. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	280 <del>300.00</del>
2	SPRAYPAINT	New	250 <del>300.00</del>
3	CHECK WIRING	New	50.00 XNN
Gross Labour Cost (S\$)			650.00

ComfortDelGro Engineering Pte Ltd/SHA9195L/29/04/2021 08:59. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA2 LKK  
29/4/2021 1320  
LIS  
2 Days  
CHECK ITEM PHOTO  
AFTER REPAIR PHOTO

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: