



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Ref: CC4/ASM21005296/Dga3q2 Date: 26/07/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7012J	Veh. Inspected	SKG 5922P	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S1M0390U	Excess (\$)	0.00	
Assign From		Assign Date	29/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT GRAND SCENIC	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VF1RFA00559516738	Colour	SILVER	
Odometer	53246 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R20	CONTINENTAL	5 mm	
L/H Front Tyre	195/55 R20	CONTINENTAL	5 mm	
R/H Rear Tyre	195/55 R20	CONTINENTAL	5 mm	
L/H Rear Tyre	195/55 R20	CONTINENTAL	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/04/2021	Inspection Date	29/04/2021	
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	