

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: YN 8716Xat Workshop m/s. GOLD BELLof 10, TUNIS AVE 18Insured: CTIPolicy No. DMCVSNW00066832000Claims No. SNM21D201713Sum Insured: _____ Excess: 450

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 49K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YN 8716X Yr Regn: 2015 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU NPR 85 U HSA c.c. 2999Colour WHITE A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JANPR85HF 7100422Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/85R16

R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7/7 mmL/Bal. 7 mm L/Bal. 7/7 mmD.O.A. 23/03/21 D.O.I. 30/04/21Survey held at GOLD BELLDes. of Damages: Fr Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 46k

04/05/21@11.36am revert to CTI via Merimen.

05/05/21@4.56pm So Chow informed C/A via Merimen.

05/05/21@5.25pm Informed wksp C/A not more than LS \$45K & ex:\$450 by email.

We will be advising our Principal a cost of repair of L/S \$45,000.00 /- with 12 days of repair,
subject to their approval. (Red \$20527, 31%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 01/03 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 12Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format : MER-ODLump Sum LBI (\$) 45000)

Goldbell Engineering Pte Ltd
Tuas Ave 18, Singapore
638892

Insurer Reference: YN8716X
Repairer Reference: 040903
Date calculated: 27/04/2021 4:48 PM

Full Report
Registration: YN8716X
Printed: 27/04/2021 4:48 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ramesh Ramesh	Currency:	SGD
Claim Reference:	YN8716X	Date of Incident:	23/03/21
Estimated Repair Time:	28	Hire Car Start:	
Actual Repair Days:	28	Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	ISUZU
Model:	N-SERIES
Sub Model:	NPR
Model Sheet Number:	37 03 03
Registration:	YN8716X
VIN number:	JAANPR85HF7100422
Odometer:	

Model Specs

AIR CONDITIONING	INTERCOOLER	3.1 LTR 74/85KW	SINGLE CAB
------------------	-------------	-----------------	------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Code	Description	WU	Price SGD
NO NUMBER	RENEW FRONT PANEL (FRONT SCREEN AND INSTRUMENT PANEL REMOVED) INCLUDES: R + R FRONT GRILLE, HEADLAMPS AND CORNER PANEL	62.0	260.40
NO NUMBER	RENEW INSTRUMENT PANEL CROSSMEMBER (COMPOSITE WORK)	22.0	92.40
NO NUMBER	RENEW HEADLAMP PANEL (COMPOSITE WORK)	32.0	134.40
NO NUMBER	R + R ATT PARTS FRONT PANEL	6.0	25.20
NO NUMBER	R + R L/F OVERRIDER	2.0	8.40
NO NUMBER	RENEW FR NUMBER PLATE (REMOVED)	2.0	8.40
NO NUMBER	R + R FRONT BUMPER	2.0	8.40
NO NUMBER	RENEW FRONT BUMPER (REMOVED)	3.0	12.60
NO NUMBER	R + R L/WIPER SHAFT	15.0	63.00
NO NUMBER	R + R LEFT WIPER ARM	8.0	33.60
NO NUMBER	RENEW L/DOOR BODY (DOOR REMOVED) INCLUDES: R + R ATTACHED PARTS OF THE DOOR, ALIGN + ADJUST DOOR	15.0	63.00
NO NUMBER	RENEW R/DOOR BODY (DOOR REMOVED) INCLUDES: R + R ATTACHED PARTS OF THE DOOR, ALIGN + ADJUST DOOR	15.0	63.00
NO NUMBER	RENEW ROOF (FRONT SCREEN AND REAR SCREEN REMOVED) INCLUDES: R + R HEADLINING, ALL ATTACHED PARTS AND TRIMS IN THE REPAIR SECTION	115.0	483.00
NO NUMBER	RENEW FRONT ROOF CROSSMEMBER	35.0	147.00
NO NUMBER	RENEW L/SIDE FRAME INCLUDES: R + R WINDSCREEN, HEADLINING, INSTRUMENT PANEL, DOOR, FRONT GRILLE, SEATS AND TRIMS IN THE REPAIR SECTION DOES NOT INCLUDE: R + R FRONT BUMPER	200.0	840.00
NO NUMBER	RENEW R/SIDE FRAME INCLUDES: R + R WINDSCREEN, HEADLINING, INSTRUMENT PANEL, DOOR, FRONT GRILLE, SEATS AND TRIMS IN THE REPAIR SECTION DOES NOT INCLUDE: R + R FRONT BUMPER	200.0	840.00
NO NUMBER	R + R REAR SCREEN	10.0	42.00
NO NUMBER	RENEW L/CAB SIDEMEMBER	84.0	352.80
NO NUMBER	RENEW R/CAB SIDEMEMBER	84.0	352.80
NO NUMBER	R + R FRONT FLOOR CARPET (FRONT SEATS REMOVED)	2.0	8.40
NO NUMBER	R + R L/WHEELHOUSE SHELL	3.0	12.60
NO NUMBER	R + R R/WHEELHOUSE SHELL	3.0	12.60
NO NUMBER	R + R COMPLETE HEATER (INSTRUMENT PANEL AND FRONT GRILLE REMOVED)	13.0	54.60
NO NUMBER	DRAIN + REFILL AIR CONDITIONING	5.0	21.00
NO NUMBER	R + R CONDENSER	10.0	42.00
NO NUMBER	R + R AIR CONDITIONING COMPRESSOR	16.0	67.20
NO NUMBER	RENEW RADIATOR (REMOVED)	13.0	54.60

Code	Description	WU	Price SGD
NO NUMBER	R + R REAR PRESSURE HOSE	5.0	21.00
NO NUMBER	R + R INTAKE HOSE	5.0	21.00
NO NUMBER	R + R RADIATOR	8.0	33.60
NO NUMBER	R + R FRONT TORSION BAR	3.0	12.60
NO NUMBER	RENEW L/F CAB BRACKET	3.0	12.60
NO NUMBER	RENEW R/F CAB BRACKET	3.0	12.60
NO NUMBER	DETACH + REFIT L/F TORSION BAR SPRING	3.0	12.60
NO NUMBER	R + R CAB CONTROL	3.0	12.60
NO NUMBER	R + R L/R LOCKING MECHANISM	3.0	12.60
NO NUMBER	R + R R/R LOCKING MECHANISM	3.0	12.60
NO NUMBER	R + R DRIVE BELT	4.0	16.80
3081	REAR CABIN PANEL REPAIR	30.0*	126.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	105.00	1,050.0	4,410.00
Total of Labour			4,410.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU Price SGD
	L/F CORNER PANEL NEW PART PAINTING	6.0
	R/F CORNER PANEL NEW PART PAINTING	6.0
	FRONT PANEL CPL NEW PART PAINTING	30.0
	CTR FRT PANEL STRUT SURFACE PAINT	5.0
	LOWER FRONT PANEL SURFACE PAINT	5.0
	L/F HEADLAMP BRACKET SURFACE PAINT	4.0
	R/F HEADLAMP BRACKET SURFACE PAINT	4.0
	L/HEADLAMP BRACKET SURFACE PAINT	4.0
	R/HEADLAMP BRACKET SURFACE PAINT	4.0
	LEFT FRONT DOOR NEW PART PAINTING	16.0
	RIGHT FRONT DOOR NEW PART PAINTING	16.0
	LEFT A-PILLAR NEW PART PAINTING	14.0
	RIGHT A-PILLAR NEW PART PAINTING	14.0
	L/OUTER B-PILLAR NEW PART PAINTING	16.0
	R/OUTER B-PILLAR NEW PART PAINTING	16.0
	ROOF NEW PART PAINTING	54.0
	FRONT ROOF FRAME SURFACE PAINT	5.0
	L/SIDE MEMBER SURFACE PAINT	4.0
	R/SIDE MEMBER SURFACE PAINT	4.0
	L/F WHEELARCH PANEL NEW PART PAINTING	12.0
	R/F WHEELARCH PANEL NEW PART PAINTING	12.0
	REAR CABIN PANEL REPAIR PAINTING <50%	24.0

Paint Material Per Part

Code	Description	Price SGD
0887	L/F CORNER PANEL NEW PART PAINTING	4.03
0888	R/F CORNER PANEL NEW PART PAINTING	4.03
0900	FRONT PANEL CPL NEW PART PAINTING	38.02
0904	CTR FRT PANEL STRUT SURFACE PAINT	4.75
0931	LOWER FRONT PANEL SURFACE PAINT	4.75
0933	L/F HEADLAMP BRACKET SURFACE PAINT	2.29

Paint Material Per Part

Code	Description	Price SGD
0934	R/F HEADLAMP BRACKET SURFACE PAINT	2.29
0937	L/HEADLAMP BRACKET SURFACE PAINT	2.29
0938	R/HEADLAMP BRACKET SURFACE PAINT	2.29
1481	LEFT FRONT DOOR NEW PART PAINTING	38.29
1482	RIGHT FRONT DOOR NEW PART PAINTING	38.29
2227	LEFT A-PILLAR NEW PART PAINTING	10.93
2228	RIGHT A-PILLAR NEW PART PAINTING	10.93
2279	L/OUTER B-PILLAR NEW PART PAINTING	15.30
2280	R/OUTER B-PILLAR NEW PART PAINTING	15.30
2351	ROOF NEW PART PAINTING	76.91
2385	FRONT ROOF FRAME SURFACE PAINT	4.75
4231	L/SIDE MEMBER SURFACE PAINT	2.11
4232	R/SIDE MEMBER SURFACE PAINT	2.11
4235	L/F WHEELARCH PANEL NEW PART PAINTING	7.87
4236	R/F WHEELARCH PANEL NEW PART PAINTING	7.87
3081	REAR CABIN PANEL REPAIR PAINTING <50%	44.00

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		275.0	
Preparation Main Work Metal	1.70	17.0	71.40
Total	10 WU/h	29.20	292.0

Material Cost - Paint

	Price SGD
New Part Painting	267.77
Repair Painting	44.00
Surface-/Blend Paint	27.63
Material-constant Metal	18.10
Total	357.50

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2001-01-01	Price SGD
4499	AIR INTAKE HOSE	8970699771	Original		180.00
2751	CAB BODY CONTROL	8978530519	Original		350.00
1000	CABIN HEAD	CABIN HEAD	Original		19,800.00
4455	COMPRESSOR	8970726624	Original		580.00
4465	CONDENSER	8971877130	Original		1,300.00
0904	CTR FRT PANEL STRUT	8975816400	Original		750.00
0281	FRONT BUMPER	8979990130	Original		360.00
0431	FRONT MANUFACT	8978595561	Original		320.00
	BADGE				
0257	FRONT NUMBER PLATE	KNPL3	Original		0.00
0900	FRONT PANEL CPL	8978592551	Original		1,150.00
1392	FRONT PANEL TRIM	8978683263	Original		350.00
2385	FRONT ROOF FRAME	8978921431	Original		350.00
6009	FRONT TORSION BAR	8973284861	Original		540.00
0410	GRILLE	8978675500	Original		256.00
0889	L/CVR PANEL SEAL KIT	8978574130	Original		120.00

	Description	Part Number	Part Source	Price SGD
33	MIS/ L/D-MIRROR BRACKET	8978537874	Original	85.00
579	L/DOOR LOCK CYLINDER	8978682420	Original	150.00
1737	MIS/ L/DOOR MIRROR	8942625433	Original	130.00
1739	MIS/ L/DOOR MIRROR ARM	8978562698	Original	120.00
1565	X L/DOOR OUTER HANDLE	8978677221	Original	130.00
1511	re/ L/DOOR SEAL	8978520932	Original	80.00
1581	? L/DOOR STRIKER	8978521061	Original	80.00
0317	bt/ L/F BUMPER BRACKET	8970936393	Original	165.00
0319	L/F BUMPER GUARD	8970767192	Original	450.00
0887	cm/ L/F CORNER PANEL	8978966540	Original	280.00
6011	bt/ L/F CTR CAB BRACKET	8970951471	Original	280.00
1505	? L/F DOOR CHECK	8975816811	Original	120.00
1717	? L/F DOOR FOIL COVER	8978523081	Original	120.00
1509	ne/ L/F DOOR FRAME SEAL	8978572065	Original	280.00
1711	cm/ L/F DOOR TRIM	8978526454	Original	230.00
1519	bro/ L/F DOOR WINDOW	8978674181	Original	580.00
0933	bt/ L/F HEADLAMP BRACKET	8975818282	Original	120.00
1571	? L/F INN DOOR HANDLE	8978666021	Original	130.00
1627	ne/ L/F INN WINDOW MLDG	8978521186	Original	130.00
2226	? L/F UPP TORSION BAR	8972618720	Original	450.00
1597	de/ L/F WINDOW CHANNEL	8978594961	Original	150.00
1547	? L/F WINDOW REGULATOR	8978521167	Original	280.00
1453	bt/ L/F WIPER ARM	8972235461	Original	125.00
1457	cut/ L/F WIPER BLADE	8971345612	Original	60.00
0937	X ? L/HEADLAMP BRACKET	8978503591	Original	130.00
1577	? L/INN DOOR LOCK	8978921982	Original	120.00
0339	? L/INN IMPACT DAMPER	8970397975	Original	540.00
2443	de/ L/INN WHEELHOUSE	8978533593	Original	380.00
1495	bt/ CVR			80.00
0605	sc/ L/LOWER DOOR HINGE	8978520075	Original	130.00
0717	? L/LOWER H-LAMP MLDG	8978983771	Original	350.00
2775	? L/POSITION LAMP	8980539780	Original	350.00
2081	? L/R LOCKING	8978530568	Original	2,580.00
4231	? L/SIDE FRAME	8978904001	Original	280.00
1487	bt/ L/SIDE MEMBER	8978500609	Original	80.00
1469	? L/UPPER DOOR HINGE	8978520075	Original	250.00
1481	? L/WIPER SHAFT	8978551540	Original	1,250.00
0561	buc/ LEFT FRONT DOOR	8975814432	Original	420.00
0931	cm/ LEFT HEADLAMP ASSY	8972071261	Original	450.00
0890	bt/ LOWER FRONT PANEL	8978507752	Original	120.00
1734	? R/CVR PANEL SEAL KIT	8978574130	Original	85.00
1580	MIS/ R/D-MIRROR BRACKET	8978537863	Original	150.00
1738	? R/DOOR LOCK CYLINDER	8978682410	Original	130.00
1740	MIS/ R/DOOR MIRROR	8942625433	Original	120.00
1512	MIS/ R/DOOR MIRROR ARM	8978565588	Original	80.00
1582	ne/ R/DOOR SEAL	8978520922	Original	80.00
0318	? R/DOOR STRIKER	8978521061	Original	165.00
0888	bt/ R/F BUMPER BRACKET	8970936393	Original	280.00
6012	cm/ R/F CORNER PANEL	8978966530	Original	280.00
1506	? R/F CTR CAB BRACKET	8970951460	Original	120.00
1718	? R/F DOOR CHECK	8975816811	Original	120.00
1510	? R/F DOOR FOIL COVER	8978523081	Original	280.00
1712	ne/ R/F DOOR FRAME SEAL	8978572055	Original	230.00
1520	cm/ R/F DOOR TRIM	8978526444	Original	580.00
	bro/ R/F DOOR WINDOW	8978674171	Original	

	Description	Part Number	Part Source	Price SGD
1548	X R/F HEADLAMP BRACKET	8975818272	Original	120.00
1548	de R/F INN DOOR HANDLE	8978666011	Original	130.00
1598	de R/F INN WINDOW MLDG	8978521176	Original	130.00
1548	? R/F WINDOW CHANNEL	8978594951	Original	150.00
1548	? R/F WINDOW REGULATOR	8978521157	Original	280.00
1454	bt R/F WIPER ARM	8972235461	Original	125.00
1458	cut R/F WIPER BLADE	8971345612	Original	60.00
0938	X R/HEADLAMP BRACKET	8978507040	Original	130.00
1578	? R/INN DOOR LOCK	8978920982	Original	120.00
0340	? R/INN IMPACT DAMPER	8971925212	Original	540.00
2444	X R/INN WHEELHOUSE CVR	8978921830	Original	380.00
1496	bt R/LOWER DOOR HINGE	8978520075	Original	80.00
0606	cut R/LOWER H-LAMP MLDG	8978983561	Original	130.00
1566	X R/OUTER DOOR HANDLE	8978677211	Original	130.00
0718	? R/POSITION LAMP	8980539770	Original	350.00
0422	X R/RADIATOR SEAL	8970610393	Original	150.00
2776	? R/R LOCKING	8978530559	Original	350.00
2082	? R/SIDE FRAME	8978904061	Original	2,580.00
4232	? R/SIDE MEMBER	8980134050	Original	280.00
1488	bt R/UPPER DOOR HINGE	8978520075	Original	80.00
1470	? R/WIPER SHAFT	8978551520	Original	230.00
7761	? RADIATOR	8971482881	Original	1,500.00
0421	? RADIATOR GRILLE SEAL	8970610393	Original	150.00
4497	? REAR PRESSURE HOSE	8971086841	Original	280.00
3151	bro REAR SCREEN	8978674270	Original	450.00
3161	X REAR SCREEN SEAL	8978531043		0.00
3162	ne REAR SCREEN SEAL	8978536541	Original	50.00
1482	bu RIGHT FRONT DOOR	8975814441	Original	1,250.00
0562	? RIGHT HEADLAMP ASSY	8972071251	Original	420.00
2351	X ROOF	8978514021	Original	1,380.00
0417	mis UP COWL PANEL GRILLE	8978927290	Original	80.00
1423	X UPPER MOULDING	8978902153		0.00
1436	? WASHER CONTAINER CPL	8978550656	Original	140.00
1401	bro WINDSCREEN	8979979452	Original	1,280.00
1410	ne WINDSCREEN SEAL	8978570487	Original	350.00
1450	? WIPER MOTOR	8973613751	Original	195.00
f: OEM Parts				0.00
n: Non-OEM Parts				55,391.00
u: Used parts				
Savings				
Subtotal				55,391.00
Total				55,391.00

Final Calculation

	SGD	SGD
Parts	55,391.00	
Total Parts		55,391.00
Labour Time Base 10 WU/h		
Total 1,050.0 WU X 42.00 SGD/h	4,410.00	
Total of Labour		4,410.00
Paint Work Time Base 10 WU/h		
Labour Cost 292.0 WU X 42.00 SGD/h	1,226.40	
Material Cost	357.50	
Total Paint Including Material		1,583.90
Repair Cost Excludes GST		61,384.90
GST (+7.0%)		4,296.94
Repair Cost Included GST		65,681.84

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ragu
Hp 90010068
12 ~~to~~ days
4/5
30/04/21 @ 1200
EXCESS: 450
Revert
Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/03/2021 16:57 (SGT)
Date of Accident	23/03/2021 19:10 (SGT)
Exact Location of Accident	11 Tuas South Ave 5, Singapore 637361
Additional Location Information	ALONG TUAS SOUTH AVE 5 BEFORE TUAS CRES JUNCT RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN8716X
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	MAY ENGINEERING PTE. LTD.
Company Reg No	2XXXXX734Z
Email Address	MAYENGINEERING@HOTMAIL.COM
Mobile Phone No	(Phone) +65-82767110
Alternative Phone No	(Office) +65-96681034

VEHICLE PARTICULARS

Manufacturer	Isuzu
Model	NPR85UH5A
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	2999

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMCVSNW00066832000
Cover Note Number	-

DRIVER

Name of Driver	ADAKKARA KUNJAPPAN SHIJO
Work Permit No	GXXXX605T

Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

20/05/1986
Outdoor
15/01/2014
7 YEARS AND 2 MONTHS
Male
(Phone) +65-82878402
-
MAYENGINEERING@HOTMAIL.COM
11 TUAS SOUTH STREET 12
#03-81
636946
No
Employee
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
DRIZZLING
Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
2
Yes
Yes
Yes
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Jurong West Neighbourhood Police Centre
(Phone) +65-18002689999
(Fax) +65-62672438
700 Corporation Road Singapore 649818
No
-

CIRCUMSTANCES OF ACCIDENT

REFERS TO POLICE REPORT NO:T/20210324/2056.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category

YP4505D
-
-
-
-
Commercial vehicle

Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person
Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?


ADAKKARA KUNJAPPAN SHIJO
-
-
-
-
SLIGHT INJURIES
YN8716X
Yes
Yes

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

QuikMAC SketchPlan Form V3

SKETCH PLAN

A: YN 8716X
B: YP 4505 D.

ALONG THAS SOUTH AVE S
BEFORE THAS CRES
JUNCT RD.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no : 7/20210324/2056.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SHARON SketchPlanForm_V3



SINGAPORE POLICE FORCE



T/20210324/2056

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20210324/2056

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/03/2021 13:07	Vide Report No.: J/20210323/0120	Station Diary No.: 73
--------------------------------------------	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: ADAKKARA KUNJAPPAN SHIJO			Address:	
ID Type / ID No.: FIN NO / G6944605T			Contact No.: Home/Office:	Mobile: 82878402
Nationality: INDIAN			Email:	
Sex: Male	Age: 34	Date of Birth: 20/05/1986	Type of Informant: Driver	
Race: Indian			Language: English	Institution / School Name:
Occupation: driver			Driving Licence Information: Class: 2B,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/03/2021 00:00	Type of Location: Straight Road
Location: TUAS SOUTH AVENUE 5				
Weather: Drizzling	Road Surface: Wet	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
YN8716X	Lorry	ISUZU	NPR85UH5A	White	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



**SINGAPORE
POLICE FORCE**



T/20210324/2056

2 of 3

Police Station Of Origin:

Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

Report No. T/20210324/2056

CONTINUATION OF REPORT

Driver			
Name	ADAKKARA KUNJAPPAN SHIJO	ID No.	G6944605T
Related Vehicle	YN8716X (Lorry)	Contact No.	82878402
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	23/03/2021	Date Discharge	23/03/2021
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 23/03/2021 at about 1910hrs, I was driving my vehicle bearing the plate number YN8716X along Tuas south ave 4 towards Tuas crescent I was at the 2nd right land and I wanted to travel to the first lane and make a right turn after which the vehicle in front of me suddenly stop and I could not break on time and collided onto the vehicle in front of me, I was then Convery Ng Teng Fong General and was given 4days of Medical leave.



**SINGAPORE
POLICE FORCE**



T/20210324/2056

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3

Report No. T/20210324/2056

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 LINUS LEOK YI QUAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt YAN-MINGSHENG DANIEL

Contact No: 65476252

SN 126

Authentication Stamp
NP168

Signature :

Singapore Police Force

Signature Of Informant:

Date/Time:

24/03/2021 13:07

Classification Of Case:

Isuzu NPR85

Overview

Financial

Accessories

Similar

Research

Photos

Map

ABWIN 論煙



Price	\$51,800	Lifespan	19-Nov-2035
Depreciation ?	\$11,380 /yr View models with similar depre	Reg Date	20-Nov-2015 (4yrs 6mths 16days COE left)
Mileage	N.A.	Manufactured ?	2015
Road Tax ?	N.A.	Transmission	Auto
Dereg Value ?	\$20,428 as of today (change)	OMV ?	\$38,568
COE ?	\$44,890	ARF ?	\$1,929
Engine Cap	2,999 cc	No. of Owners ?	3
Curb Weight ?	2,500 kg		
Type of Vehicle	Truck		

ED HISTORY



Fe

Compare

Fr

With Two Slide Doors. Monzone Brand. Can Go Till -15 Degree Celsius. Beautiful Bidded Car



ASUS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	734Z
Vehicle No.:	YN8716X
Vehicle to be Exported:	No
Intended Deregistration Date:	03 May 2021
Vehicle Make:	ISUZU
Vehicle Model:	NPR85UH5A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4JJ11Z1889
Chassis No.:	JAANPR85HF7100422
Maximum Power Output:	-
Open Market Value:	\$29,226.00
Original Registration Date:	25 Aug 2015
First Registration Date:	25 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$1,462.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	24 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,064.00
COE Rebate Amount:	\$2,180.00
Total Rebate Amount:	\$2,180.00

The information contained herein is correct as at 03 May 2021

OK

White