

ASS. REC. BY:


ECICS/21005318/Kuf3

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP/WS/TP RES/OD RES/EVA/INV/MY)
 To Inspect Vehicle No: GBH 5741X
 at Workshop m/s: City Ave
 of _____
 Insured: SLF 3820G
 Policy No. _____
 Claims No. DMPC2100146H/02/CT
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 355k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 18 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN/OUT

Veh No: GBH 5741K Yr Regn: 07 18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: NIS NV200 c.c. 1461
 Colour: White A/C: Insured / Std / Nil / NA
 Sp. Reading: 27886 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: VM 20 - 123114
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rlm / STD A/Rlm or
 Tyre Size: F: 165/80R14
 R: _____
 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 8 mm Rear R/Bal. 6 mm
 L/Bal. 8 mm L/Bal. 6 mm
 D.O.A. 20/4/21 D.O.I. 30/4/2021
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 NIS
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
3/5/2021 @ 11.03am	Revised to ECICS via Merimen.

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	_____
Transportation:	_____
S - RS - SI	_____
Fees	_____
Others	_____
TOTAL	_____

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202104-000971(00)

Date : 29/04/2021

Vehicle No. : GBH5741X

Make/Model : NISSAN NV200 DX-2 1.6 AUTO

Mileage (km) : 0

Chassis No. : VM20123114

Accident Date : 20/04/2021 00:00:00

Claim No. : SLF3820G

Reference : JO202104-1198

Policy No. : 5114098177-01

ECICS LIMITED

NO. 10

EUNOS RD 8 #09-04A
SINGAPORE POST CENTRE
SINGAPORE 408600

Contact : -

Fax No. : 63389267

NOT Attached
1/1 Day &
Money After Pain
18 days

S/No	Particular	Quantity	Unit Price	Amount S\$
NET ITEMS :				
1	Bonnet	1.0	580.00	580.00 ✓
2	Bonnet hinge	2.0	85.00	170.00 ✓
3	Bonnet lock	1.0	98.00	98.00 ✓
4	Front headlamp	2.0	320.00	640.00 ✓
5	Front headlamp lower garnish	2.0	185.00	370.00 ✓
6	Front grille	1.0	325.00	325.00 ✓
7	Front grille logo	1.0	48.00	48.00 ✓
8	Front grille moulding	1.0	85.00	85.00 ✓
9	Front bumper	1.0	385.00	385.00 ✓
10	Front bumper side retainer	2.0	42.00	84.00 ✓
11	Front bumper reinforcement	1.0	425.00	425.00 ✓
12	Front bumper lower guard	1.0	145.00	145.00 ✓
13	Front bumper tow cover	1.0	35.00	35.00 ✓
14	Front fender inner shield LH	1.0	115.00	115.00 ✓
15	Front headlamp panel	2.0	58.00	116.00 ✓
16	Support panel	1.0	450.00	450.00 ✓
17	Air con condenser	1.0	585.00	585.00 ✓
18	Radiator assy	1.0	550.00	550.00 ✓
19	Fan cowling	1.0	185.00	185.00 ?
20	Fan motor	1.0	280.00	280.00 ?
21	Fan blade	1.0	90.00	90.00 ?
22	Front wheel cover LH	1.0	115.00	115.00 ✓
23	Front shock absorber LH	1.0	225.00	225.00 ✓
24	Front knuckle arm LH	1.0	285.00	285.00 ✓
25	Front lower arm LH	1.0	265.00	265.00 ✓
26	Front wheel bearing - LH	1.0	115.00	115.00 ✓
27	Front linkage LH	1.0	85.00	85.00 ?
28	Tie rod end - LH	1.0	90.00	90.00 ?
29	Steering rack end - LH	1.0	155.00	155.00 ?
30	Engine under cover - LH	1.0	180.00	180.00 ✓
31	Engine under cover - RH	1.0	180.00	180.00 ?
32	Fuse box cover - top	1.0	155.00	155.00 ?
33	Fuse box cover - bottom	1.0	195.00	195.00 ?
34	Auto gear box	1.0	1,850.00	1,850.00 ?

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202104-000971(00)

ECICS LIMITED
NO. 10
EUNOS RD 8 #09-04A
SINGAPORE POST CENTRE
SINGAPORE 408600

Date : 29/04/2021
Vehicle No. : GBH5741X
Make/Model : NISSAN NV200 DX-2 1.6 AUTO

Contact : - Fax No. : 63389267

Mileage (km) : 0
Chassis No. : VM20123114
Accident Date : 20/04/2021 00:00:00
Claim No. : SLF3820G
Reference : JO202104-1198
Policy No. : 5114098177-01

S/No	Particular	Quantity	Unit Price	Amount S\$
35	Drive shaft - LH	1.0	685.00	685.00 ?
36	Front cross member	1.0	650.00	650.00 ?
37	Steering air bag	1.0	850.00	850.00 ✓
38	Passenger air bag	1.0	950.00	950.00 ✓
39	Front seat belt	2.0	385.00	770.00 ✓
40	SRS control module	1.0	600.00	600.00 ✓
41	Front brake pipe - LH	1.0	195.00	195.00 ?
42	Engine mounting set	1.0	485.00	485.00 ?
List Total :				14,841.00
10% Discount S\$				1,484.10
				13,356.90
SPECIAL NET :				
1	Front rim LH	1.0	250.00	250.00 ?
SPECIAL NET Total S\$:				250.00
LABOUR :				
	- To remove and install front suspension	1.0	250.00	250.00 2000
	- To conduct wheel alignment	1.0	60.00	60.00 ✓
	- To remove and install engine and gear box to carry out repair on front portion	1.0	300.00	300.00 2500
	- To remove and install air bags, seat belt and SRS control module	1.0	250.00	250.00 2000
	- To recharge air con gas	1.0	120.00	120.00 1000
	- To check and repair wire harness	1.0	150.00	150.00 ?
	-To knock jackout damaged parts, panel beating,welding, align, refix and to renew accident parts	1.0	2,500.00	2,500.00 2000
	- Spray painting on affected & replace parts	1.0	1,200.00	1,200.00 11000
	* Towing charge	1.0	60.00	60.00 ✓
				4,890.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/04/2021 17:08 (SGT)
Date of Accident	20/04/2021 10:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JUNCTION OF BOON LAY WAY AND JURONG GATEWAY ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH5741X

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CHAN'S & SONS ENTERPRISE
Company Reg No	XXXXXX00M 51936900M
Email Address	joyce@chans.com.sg
Mobile Phone No	(Phone) +65-96853795
Alternative Phone No	+65-96853795

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Nv200
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	1597

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	5114098177-01
Cover Note Number	-

DRIVER

Name of Driver	CHUA CHEW ONG (CAI QIUWANG)
NRIC No	SXXXX616A

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes"

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



CITY AUTO PTE LTD

Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1745 Fax: 6453 7944
(Claims Section)

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Jurong gateway Road

Boon Lay Way

A - GBH 5741X

b - SLF 38206