

ASS. REC. BY:

64  
PRS

ASSIGNMENT

(31 Jan 2010)

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Teamwerk garage  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SJV4163 C Yr Regn: 26 Jan 2010  
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mit Lancer 1.6 c.c 1584  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 162225 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JMYSNCS3A 94004800  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195 (60R15 (Rapid))  
 R: 11 (Yoko)

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.  
 Bal. or Market Value: \$23K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 30-04-21  
 Survey held at W/S 4pm  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_  
Frt o/s  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Rebate: 9516
	\$2000 - \$3000
	SUBMIT PRS REPROT

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 3  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Insp (\$) \_\_\_\_\_  
 : Material (\$) \_\_\_\_\_

Survey Fee:	
Transportation:	
Photos	
Other:	

Report Final: PRS