

ASS. REC. BY:

REF: CS3/LPC20009991/Eqf3-1

Special Instruction:

Surveyor: STEVE

ASSIGNMENT (Office)

From (Person): ONG LI LI of LPC Date/Time: 17/9/2020 2:56 PM

Estimated Cost: Bill to:

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJT 4425H Insured: YP 137J

at Workshop m/s Garage 13 Pte Ltd Tel: 6385 1171

of 8 kaki bukit ave 4 # 03-46 PREMIER

Policy No: Claim No: 20/20/20/VC00/023679

Sum Insured: Excess:

Make of Veh: D.O.A. 15.09.2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement:

Date/Time: 17-9-20 3.36P.M Person Contacted: IRENE Vehicle IN  OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJT 4425H- CS3/AXA16005384/Gh3d1 DOA:19/03/2016
	YP 137J- X