

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

ALB (CRP)

Date: 30.04.2021
Time: 16:24:11
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305466560
REGN NO : SHA7772J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 27.08.2020
DATE/TIME IN : 30.04.2021 08:55
ACCIDENT DATE : 29.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	Ry	
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	de	
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	K	nm
0004	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	X	nm
0005	FNPS	NUMBER PLATE W/CASING	1 N	50.00	0.20	50.00	nm	
							SUB-TOTAL : 846.12	

JOB NATURE

0000	PB	PANEL BEATING	400.00	350	
0001	SP	SPRAYPAINT CHARGE	300.00	250	630
0002	L	REMOVE/REFIX REVERSE SENSOR	80.00	30	

SUB-TOTAL : 780.00

\$1041

2 days

Tanpin 97495749
WP 3/5/21 e 1230

2 days

P/P, Resurvey new parts, after
tanpin @ lkhauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: