



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21005358/Uuf3n2 Date: 07/05/2021	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SDS 1812U	Veh. Inspected	SMS 951B
Policy No.		Coverage (\$)	0.00
Claim No.	C10010068/HA	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	30/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA CRV (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHLRE2850AAC200632	Colour	BLACK
Odometer	158253 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/65 R17	MICHELIN	6 mm
L/H Front Tyre	225/65 R17	MICHELIN	6 mm
R/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	29/04/2021	Inspection Date	30/04/2021
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	