



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Isuzu Nhr69e (YP6951K)
Date of Loss	26 April 2021
Time of Loss	17:35
Loss Description	SJH4072E (INSD) C/W YP6951K (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	\$0.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# YP6951K

Registration State SINGAPORE

Mileage 262969

Purchase Date DD/MM/YYYY



Registration Date * 24/07/2017



Age of Vehicle 3

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2017

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

SRIGANESH
RENGASAMY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Isuzu	<input type="text" value="ISUZU"/>
Model	Nhr69e	<input type="text" value="NPR75UK5W"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JAANPR75KH7101437"/>
Engine No		<input type="text" value="4HK1584950"/>
Engine Capacity		<input type="text" value="5193"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	6 February 1977	<input type="text" value="DD/MM/YYYY"/> 
Age	44	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	G7602016M	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

03/05/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

215/85R16

YOKOHAMA8mm

YOKOHAMA8mm

215/85R16(D)

YOKOHAMA3/3mm

YOKOHAMA3/3mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages

Claims













Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTI (PAR
	0	1		TAILLAMP ASSY RH	Cut	0	450	No	0	10	0	0	405	Rev
	0	1		REAR MUDFLAP RH	Cracked	0	468	No	0	10	0	0	421.2	Rev
	0	1		REAR MUDFLAP BRACKET INNER RH	Repair	0	0	No	0	0	0	0	0	Den
	0	1		REAR MUDFLAP BRACKET OUTER RH	Repair	0	0	No	0	0	0	0	0	Den
	0	1		REAR MUDFLAP LOWER RUBBER - ISUZU RH	Cracked	0	180	No	0	10	0	0	162	Rev

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTI (PAR
	0	1		REAR WHEEL BEARING RH INNER	Serviceable	0	0	No	0	0	0	0	0	Den
	0	1		REAR WHEEL BEARING RH OUTER	Serviceable	0	0	No	0	0	0	0	0	Den
	0	1		REAR AXLE	Serviceable	0	0	No	0	0	0	0	0	Den
	0	1		REAR AXLE SPRING 1SET RH	Serviceable	0	0	No	0	0	0	0	0	Den
	0	1		REAR AXLE SPRING BRACKET RH	Repair	0	0	No	0	0	0	0	0	Den
	0	1		REAR CENTRE SHAFT	Serviceable	0	0	No	0	0	0	0	0	Den
	0	2		REAR SHAFT BRACKET	Serviceable	0	0	No	0	0	0	0	0	Den
	0	1		REAR WHEEL SHAFT RH	Serviceable	0	0	No	0	0	0	0	0	Den

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTI (PAR
	0	1		REAR WHEEL SHAFT WHEEL BEARING RH	Serviceable	0	0	No	0	0	0	0	0	Den
	0	1		REAR NO PLATE LAMP	Broken	0	180	No	0	10	0	0	162	Rev
	0	1		EXHAUST REAR	Bent	0	980	No	0	10	0	0	882	Rev













Labour









Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	0	1200	0	0	Reviewing		
	0		SPRAY PAINTING ON ACCIDENT AREA	0	680	0	0	Reviewing		
	0		R&R CRANE TO SERVICE TO LIFT UP & DOWN	0	0	0	0	Deny		
	0		R&R REAR SUSPENSION RH	0	0	0	0	Deny		
	0		CHECK & REPAIR WIRING SYSTEM	0	20	0	0	Reviewing		
	0		RESPRAY TUFF KOTE ON AFFECTED AREA	0	0	0	0	Deny		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		CONDUCT CHASSIC REPAIR REAR RH PORTION	0	0	0	0	Deny		
	0		R&R REAR AXLE, AXLE SPRING & LONG SHAFT TO ASSIT REPAIR	0	0	0	0	Deny		
	0		RESET & REPROGRAMME LTA SYSTEM & INSPECTION	0	0	0	0	Deny		
	0		POST ACCIDENT REPAIR INSPECTION	0	0	0	0	Deny		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition











Taxes & Ratio











Parts & Labour










Miscellaneous













Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 7 DAYS	Reviewing	0	0		
	0	REAR CABIN ASSY RH	Reviewing	0	3000	BENT	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR CABIN TAILLAMP PANEL RH	Deny	0	0	NO SUCH PART	
	0	REAR TOP PANEL ALUMINIUM RH - 3PCS	Reviewing	0	400	DENTED (1PC ONLY)	
	0	REAR STICKER 60KM	Deny	0	0	NOT NECESSARY	
	0	REAR REFLECTOR STICKER - RED	Reviewing	0	40	NECESSARY	
	0	REAR REFLECTOR STICKER SIDE RH - BLUE & ORANGE	Reviewing	0	100	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR FENDER MUDFLAP BRACKET RH (FRONT)	Deny	0	0	REPAIR	
	0	REAR FENDER MUDFLAP BRACKET RH (REAR)	Deny	0	0	REPAIR	
	0	REVERSE CAMERA	Deny	0	0	SERVICEABLE	
	0	REAR TYRE RH INNER - 215/85/R22	Deny	0	0	SERVICEABLE	
	0	REAR TYRE RH OUTER - 215/85/R22	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR RIM RH INNER	Deny	0	0	SERVICEABLE	
	0	REAR RIM RH OUTER	Deny	0	0	SERVICEABLE	
	0	REAR CRANE	Deny	0	0	REPAIR	
	0	REAR CRANE FORK	Deny	0	0	REPAIR	
	0	REAR SPRING BRACKET	Deny	0	0	REPAIR	
	0	REAR CABIN TAILLAMP WIRE HARDNESS	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	HYDRALIC OIL	Deny	0	0	NOT NECESSARY	
	0	1 SET REVERSE SENSOR	Deny	0	0	NO SUCH PART	
	0	EXHAUST SILENCER	Reviewing	0	1900	BENT	
	0	EXHAUST CENTRE	Deny	0	0	REPAIR	
	0	REAR NUMBER PLATE	Reviewing	0	15	BENT	
	0	REAR NUMBER PLATE BRACKET	Reviewing	0	150	BENT	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$9,537.20
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$2,032.20
Labour	\$0.00	\$1,900.00
Miscellaneous	\$0.00	\$5,605.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

6000



[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$6,000.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$6,000.00

Submit for Review