

ASS. REC. BY:

REF:

Asny 21005374/Kuc

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: YP 6951K

at Workshop m/s S7hree

Insured: SJH 4072E

Policy No. \_\_\_\_\_

Claims No. S1M0394Z


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 877k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: YP 6951K Yr Regn: 07, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki NPR75 c.c. 5193

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 282865 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JAA NPR 75KH 7101437

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/85R16  
R: \_\_\_\_\_ (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 3 3 mm

L/Bal. 8 mm L/Bal. 3 3 mm

D.O.A. 26/4/21 D.O.I. 3/5/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5/21 @ 2.24pm Revise to Tan Wangcong via Smart Claim.

8/6/21 Rm 86000 Confirm 7 repair days.

(RED \$64,210.20; 91%)

Date/Time, File Pass to?

☐ : Prell. Report

1) 21/6 TYPIST

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

S - RS. \$

Fares

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format: TP

Lump Sum / L.B. (\$) 6000



# S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorized  
C1 Sing 86000p  
Recovery After Pains  
Folay

TO :  
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SJH4072E

ESTIMATE REPOR 1st QUOTATION

JOB NO. : \_\_\_\_\_

## OWNER'S PARTICULAR

NAME : CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD

CONTACT : \_\_\_\_\_

ADDRESS : \_\_\_\_\_

VEHICLE N° YP6951K TRANS. :

CHASSIS NO. :

MAKE / MODEL : ISUZU LORRY

ENGINE NO. :

OWNER'S INSURE FIRST CAPITAL

JOB-CODE : TP S/A :

ACCIDENT DATE : 26-Apr-21

## CLAIM DETAIL

### MATERIALS

		QTY	QUO-PRICE	DISC %	DISC-PRICE	SUR	REV. PRICE
1	TAILLAMP ASSY RH	CU	1.00 \$ 450.00	10.00	\$ 405.00	Y	✓
2	REAR MUDFLAP RH 468.00	CM	1.00 \$ 520.00	10.00	\$ 468.00	Y	✓
3	REAR MUDFLAP BRACKET INNER RH	K	1.00 \$ 220.00	10.00	\$ 198.00	Y	X
4	REAR MUDFLAP BRACKET OUTER RH	K	1.00 \$ 220.00	10.00	\$ 198.00	Y	X
5	REAR MUDFLAP LOWER RUBBER - ISUZU RH	CM	1.00 \$ 180.00	10.00	\$ 162.00	Y	✓
6	REAR WHEEL BEARING RH INNER	nn	1.00 \$ 450.00	10.00	\$ 405.00	Y	X
7	REAR WHEEL BEARING RH OUTER	nn	1.00 \$ 450.00	10.00	\$ 405.00	Y	X
8	REAR AXLE	Sn	1.00 \$ 13,500.00	10.00	\$ 12,150.00	Y	X
9	REAR AXLE SPRING 1SET RH	Sbe	1.00 \$ 650.00	10.00	\$ 585.00	Y	X
10	REAR AXLE SPRING BRACKET RH	R	1.00 \$ 208.00	10.00	\$ 187.20	Y	X
11	REAR CENTRE SHAFT	Sn	1.00 \$ 8,850.00	10.00	\$ 7,965.00	Y	X
12	REAR SHAFT BRACKET 2PCS	Sn	1.00 \$ 240.00	10.00	\$ 216.00	Y	X
13	REAR WHEEL SHAFT RH	Sn	1.00 \$ 980.00	10.00	\$ 882.00	Y	X
14	REAR WHEEL SHAFT WHEEL BEARING RH	nn	1.00 \$ 280.00	10.00	\$ 252.00	Y	X
15	REAR NO PLATE LAMP	Bu	1.00 \$ 180.00	10.00	\$ 162.00	Y	✓

TOTAL (PARTS) :

\$ 27,378.00

\$ 24,640.20

### SPECIAL NETT ITEM

1	REAR CABIN ASSY RH	Bz	1.00 \$ 12,800.00	0.00	\$ 12,800.00	Y	30000
2	REAR CABIN TAILLAMP PANEL RH	NSP	1.00 \$ 680.00	0.00	\$ 680.00	Y	X
3	REAR TOP PANEL ALUMINIUM RH 2PCS	nd	1.00 \$ 1,200.00	0.00	\$ 1,200.00	Y	LX
4	REAR STICKER 60KM	na	1.00 \$ 30.00	0.00	\$ 30.00	Y	X
5	REAR REFLECTOR STICKER - RED	na	1.00 \$ 180.00	0.00	\$ 180.00	Y	4000
6	REAR REFLECTOR STICKER SIDE RH- BLUE & ORANGE	na	1.00 \$ 360.00	0.00	\$ 360.00	Y	10000



7	REAR FENDER MUDFLAP BRACKET RH (FRONT)	1.00	\$	180.00	0.00	\$	180.00	Y	X
8	REAR FENDER MUDFLAP BRACKET RH (REAR)	1.00	\$	180.00	0.00	\$	180.00	Y	X
9	REVERSE CAMERA	1.00	\$	380.00	0.00	\$	380.00	Y	X
10	REAR TYRE RH INNER - 215/85/R22	1.00	\$	380.00	0.00	\$	380.00	Y	X
11	REAR TYRE RH OUTER - 215/85/R22	1.00	\$	380.00	0.00	\$	380.00	Y	X
12	REAR RIM RH INNER	1.00	\$	680.00	0.00	\$	680.00	Y	X
13	REAR RIM RH OUTER	1.00	\$	680.00	0.00	\$	680.00	Y	X
14	REAR CRANE	1.00	\$	9,500.00	0.00	\$	9,500.00	Y	X
15	REAR CRANE FORK	1.00	\$	2,800.00	0.00	\$	2,800.00	Y	X
16	REAR SPRING BRACKET	1.00	\$	650.00	0.00	\$	650.00	Y	X
17	REAR CABIN TAILLAMP WIRE HARDNESS	1.00	\$	860.00	0.00	\$	860.00	Y	X
18	HYDRALIC OIL	1.00	\$	450.00	0.00	\$	450.00	Y	X
19	REVERSE SENSOR ISET	1.00	\$	520.00	0.00	\$	520.00	Y	X
20	EXHAUST SILENCER	1.00	\$	1,900.00	0.00	\$	1,900.00	Y	✓
21	EXHAUST CENTRE	1.00	\$	1,080.00	0.00	\$	1,080.00	Y	X
22	EXHAUST REAR → 108	1.00	\$	980.00	0.00	\$	980.00	Y	✓
23	REAR NUMBER PLATE	1.00	\$	50.00	0.00	\$	50.00	Y	1552
24	REAR NUMBER PLATE BRACKET	1.00	\$	150.00	0.00	\$	150.00	Y	✓

TOTAL (PARTS) :

\$ 37,050.00

\$ 37,050.00

#### LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	\$	2,600.00	0.00	\$	2,600.00	Y	12001
2	SPRAY PAINTING ON ACCIDENT AREA (2 times)	1.00	\$	1,600.00	0.00	\$	1,600.00	Y	6801
3	R&R CRANE TO SERVICE TO LIFT UP & DOWN	1.00	\$	480.00	0.00	\$	480.00	Y	X
4	R&R REAR SUSPENSION RH	1.00	\$	380.00	0.00	\$	380.00	Y	X
5	CHECK & REPAIR WIRING SYSTEM	1.00	\$	80.00	0.00	\$	80.00	Y	201
6	RESPRAY TUFF KOTE ON AFFECTED AREA	1.00	\$	120.00	0.00	\$	120.00	Y	X
7	CONDUCT CHASSIC REPAIR REAR RH PORTION	1.00	\$	1,200.00	0.00	\$	1,200.00	Y	X
8	R&R REAR AXLE, AXLE SPRING & LONG SHAFT TO ASSIT REPAIR	1.00	\$	900.00	0.00	\$	900.00	Y	X
9	RESET & PROGRAMME LTA SYSTEM & INSPECTION	1.00	\$	980.00	0.00	\$	980.00	Y	X
10	POST ACCIDENT REPAIR INSPECTION	1.00	\$	180.00	0.00	\$	180.00	Y	X

TOTAL (LABOUR) :

\$ 8,520.00

\$ 8,520.00

TOTAL PARTS & LABOUR

\$ 72,948.00

\$ 70,210.20

**LKK Auto Consultants** hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EXCESS : : S\$ \_\_\_\_\_

NO. OF DAY : \_\_\_\_\_

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$ \_\_\_\_\_

DATE OF SURVEY : \_\_\_\_/\_\_\_\_/\_\_\_\_

SURVEY BY : \_\_\_\_\_

CONTACT : \_\_\_\_\_

FAX NO : \_\_\_\_\_

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	28/04/2021 11:23 (SGT)
Date of Accident	26/04/2021 17:35 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	TOWARDS AYE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP6951K
-----------------------------	---------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Company Reg No	2XXXXX882K
Email Address	JEREMYC_QUEK@CERTISSECURITY.COM
Mobile Phone No	(Phone) +65-68428849
Alternative Phone No	(Office) +65-68428849

#### VEHICLE PARTICULARS

Manufacturer	Isuzu
Model	Nhr69e
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	3000

#### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	D-21097604MFVS/13
Cover Note Number	-

#### DRIVER

Name of Driver	SRIGANESH RENGASAMY
Work Permit No	GXXXX016M



Date Of Birth	02/06/1977
Occupation	Outdoor
Date Of Driving Pass	06/07/2012
Driving experience	8 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-84544284
Alt. Phone Number	-
Email Address	JEREMYQC_QUEK@CERTISSECURITY.COM
Address	20 JALAN AFIFI
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Geylang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18008486999
Alt. Police Station Phone No	(Fax) +65-68486799
Police Station Address	1 Cassia Link Singapore 397618
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO POLICE REPORT.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH4072E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-





SKETCH PLAN #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

--- AS per Police Report ---

DECLARATION

I/We declare the foregoing particulars are true to my/our best knowledge.

Psychologist's Signature  
Date: 11/11/11

Driver's Signature  
I declare that the police statement  
is true to my best knowledge.

Witness 1's Signature  
Date: 11/11/11

Psychologist

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



7/0021042862174

1 of 1

Police Station Of Origin  
Geylang M P C  
1 Cassia Link SINGAPORE 397618  
Tel No: 1000-6488888

Report No: 1-2921042862134

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:  
26/04/2021 22:12

Video Report No: 1

Station Diary No.:  
121

## Informant's Particulars

Name of Informant: SRICANESH RENGASAMY			Address: 1 MARITIME SQUARE #09-36 HARBOURFRONT CENTRE SINGAPORE 099253	
ID Type / ID No.: FIN NO / G7602016M			Contact No.: Home/Office: Mobile: 845-44284	
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 43	Date of Birth: 02/06/1977	Type of Informant: Driver	
Race: Indian			Language: English	
Occupation: EMAS RECOVERY OFFICER			Institution / School Name: Date of Expiry:	
			Driving Licence Information: Class: 2B, 3, 4, 5	

## General Information of the Accident

Type of Accident:	Injury: Attended by Police	Drink Drive: No	Date/Time of Accident: 26/4/21 17:55	Type of Location: Straight Road
----------------------	-------------------------------	-----------------------	--	------------------------------------

Location:

CENTRAL EXPRESSWAY

Weather: Drizzling	Road Surface: Wet	Road Speed Limit:
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear		Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJH4072E	Car				Seriously Damaged	0
YP5951K	EMAS Tow Truck				Slightly Damaged	0

## Details of Person Involved

Any Pedestrian Involved: No  
No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



SINGAPORE  
POLICE FORCE



T:20210426/2134

2 of 3

Police Station Of Origin:  
Gaylang N.P.O.  
1 Cassia Link SINGAPORE 397818  
Tel No: 1800-8486999

Report No: T20210426/2134

## CONTINUATION OF REPORT

Driver Name		LEE KENG YAN		ID No	535131430
Related Vehicle		SJH4072E (Car)		Contact No	NIL
Hospital/Clinic		NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment		NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL		Degree of Injury	Slight
Driver Name		SRICANESH RENGASAMY		ID No	G7602016M
Related Vehicle		YP6951K (EMAS Tow Truck)		Contact No	84544284
Hospital/Clinic		NIL		Class of Driving Licence & Expiry Date	Class: 2B, 3, 4, 5 Date of Expiry: NIL
Date Treatment		NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL		Degree of Injury	NIL

## Brief Details:

On 26/04/2021 at about 1735hrs, I was activated to attend to a case of an obstacle at CTE towards AVF near the 5.3km mark, on Lane 4. Together with the traffic marshal, we proceed to the scene from Moulmein and arrived there at 1754hrs.

As we reached the scene, we carried out the necessary standard procedures and my co-driver then went down from the truck and extracted the obstacle on the road which was in front of my truck, which was a broken plywood. At the same time, I was donning my PPE inside the truck when I felt an impact from the rear of my truck. I then went down from my truck and realized that one blue colour car had hit the rear of my truck causing the front part of the car to be seriously damaged. I then made a check on my truck and realized that the right rear of my truck was slightly damaged.

The car driver complained of knee pain however there were no visible injuries. We also activated the ambulance through our IPSC and shortly ambulance arrived and made a check on the car driver. No conveyance was required.

Neither my co-driver nor myself sustained any injuries. We were then advised by my company to lodge a traffic accident report.





SINGAPORE  
POLICE FORCE



T/20210426/2134

Police Station Of Origin  
Gaylang N.P.C.  
Cassia Link SINGAPORE 397613  
Tel No: 1800-8466999

4 of 4  
Report No: T/20210426/2134

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report  
G/

Sr Staff Sgt AHMAD ZAHID BIN JASNI

Signature Of Informant

Signature Of Interpreter  
Not applicable

Date/Time  
26/04/2021 22:12

Officer In Charge Of Case:  
TP / GIT /  
Staff Sgt NUR ADELINA BINTE MOHAMMAD  
FUAT  
Contact No: 65476655  
Authentication Stamp  
UP 106

Classification Of Case

**CERTIFICATE OF INSURANCE**

ORIGINAL

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Type of Policy. : FLEET - HEAVY COMMERCIAL VEHICLE ...  
Type of Cover. : Comprehensive  
Certificate No. : D-21097604MFVS/13  
Vehicle No / Chassis No : YP6951K / JAANPR75KH7101437  
Name of Insured : LAND TRANSPORT AUTHORITY  
Period Of Insurance : 26.04.2021 To 25.04.2022  
Insured Estimated Value : Market Value At Time Of Loss

**Excess :**

SGD3,000.00 SECTION I & II SEPARATELY  
ADDITIONAL SGD3,000.00 SECTION I & II SEPARATELY IS APPLICABLE TO ANY NAMED OR  
UNNAMED DRIVERS AGE 22 TO 24 YEARS OLD AND/OR AGE 66 TO 70 YEARS OLD AND/OR  
WITH DRIVING EXPERIENCE OF LESS THAN 2 YEARS IN SINGAPORE ON THE RELEVANT  
CLASSES OF DRIVING LICENCE  
SGD600.00 WINDSCREEN

**Authorised Driver\***

ANY AUTHORISED DRIVERS

**Persons or classes of persons entitled to drive\***

Any person who is driving on the Insured's order or with their permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**Limitations as to use\***

Use in connection with the Insured's business.

Whilst the Motor Vehicle is being so used the carriage of passengers is permitted.

The Policy does not cover

- (1) Use for racing, pace-making, reliability trial or speed-testing.
- (2) Use for the carriage of passengers for hire or reward
- (3) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

MS First Capital Insurance Limited  
(Approved Insurers)

JORDINE/B0029/MZ801

Issued at Singapore on 23.04.2021

  
\_\_\_\_\_  
Authorised Signature

**Vehicle General Information** ▼**Enquire Vehicle & Owner Information****Owner Details (The latest record from Vehicle Master)**

Owner ID Type:	Statutory Board
Owner ID:	T08GB0027D
Owner ID (Before UEN/FIN):	C060800A
Owner Name:	LAND TRANSPORT AUTHORITY
Name Effective Date:	-
Source of Name:	-
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	1
Registered Street Name:	HAMPSHIRE ROAD
Registered Unit No.:	-
Registered Building Name:	-
Registered Postal Code:	219428
Registered Address Effective Date:	25 Mar 2015
Registered Address Source:	Address supplied by public to LTA/supplied by MyInfo
Email Address:	-
Birth Date:	-

**Current Vehicle Details**

Vehicle No.:	YP6951K
Status:	Registered
Vehicle Type:	B76 - Goods (Open) Recovery Vehicle
Vehicle Scheme:	Normal
Original Vehicle Scheme:	Normal
Last Conversion Date:	-
Vehicle Attachment 1:	No Attachment
VITAS Approval Code:	201706136621RA
Engine No.:	4HK1584950
Chassis No.:	JAANPR75KH7101437
Make/Model:	ISUZU / NPR75UK5W
Primary Colour:	White
IU Label No.:	1510962053
Engine Capacity:	5193 cc
Maximum Power Output:	-
Passenger Capacity:	6
Propellant:	Diesel
Emission Standard Code:	Euro V
Maximum Laden Weight:	7900 kg
Unladen Weight:	4740 kg
No. Of Axles:	2
Front Tyre Information:	215/85R16
Rear Tyre Information:	215/85/R16(D)
Year of Manufacture:	2017
Foreign Original Registration Date:	-
Foreign Original De-registration Date:	-
Original Registration Date:	24 Jul 2017
First Registration Date:	24 Jul 2017
Effective Ownership Date From:	24 Jul 2017
Effective Ownership Date To:	-



Transfer Count: 0  
 Open Market Value: \$44,779.00  
 Full ARF Price: \$0.00  
 Additional Registration Fee Rate: 5.00 %  
 Actual ARF Paid: \$2,239.00  
 PARF Eligibility: No  
 Minimum PARF Benefit: -  
 Lifespan Expiry Date: No Lifespan  
 COE-Exempted: No  
 COE No.: 2017080105000128C  
 Bidding Type: Open  
 Bidding Exercise No.: 1  
 COE Bid Category: C - Goods Vehicle & Bus  
 Quota Premium (QP): \$40,212.00  
 QP Paid: \$40,212.00  
 COE Bid Deposit: \$10,000.00  
 Balance Bid Amount: \$30,212.00  
 Bid Amount: \$42,000.00  
 COE Registration Category: C - Goods Vehicle & Bus (51)  
 QP (Regn Cat): \$40,212.00  
 PQP Indicator: No  
 COE Issue Date: 24 Jul 2017  
 COE Expiry Date: 23 Jul 2027  
 OPC Cash Rebate Eligibility: No  
 QP during COE Bidding Exercise: \$40,212.00  
 Vehicle De-reg and Re-reg in Singapore: No  
 Green Vehicle Rebate Eligibility: No  
 Actual Green Vehicle Rebate Utilised Amount:-  
 Green Vehicle Rebate Top-up Amount: -  
 CO2 Emission: -  
 CO Emission: -  
 HC Emission: -  
 NOx Emission: -  
 PM Emission: -

#### Vehicle Exemption Information

Exemption Type:	COE	RF	ARF	Road Tax	Insurance	Inspection	Seal Inspection	VPC
Vehicle Master Indicator:	No	No	No	No	N/A	N/A	N/A	Yes

#### Insurance Details (As At 04 Jul 2018 / 15:13:42)

Insurance Company Name: GREAT EASTERN GENERAL INSURANCE LIMITED  
 Policy Start Date: 24 Jul 2017  
 Policy End Date: 23 Jul 2018  
 Policy Holder Name: LAND TRANSPORT AUTHORITY