

ASS. REC. BY:

CS/  
REF:

UOL/ 210053751Kvf3

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. DHOM110167801901


Claims No. M11D12482104

Sum Insured: \_\_\_\_\_ Excess: 5000 ?

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: B300k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 24 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: EY 12005 Yr Regn: 10, 89

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Spot CarMake: Porsche 911 c.c. 3600Colour: M.L. Blue A/C: Insured / Std / NI / NASp. Reading: 12649 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WPO 222 962KS 401672Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD / R/Rim orTyre Size: F: 225/45 ZR17R: 265/40 ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 8 mm R/Bal. 4 mmL/Bal. 8 mm L/Bal. 4 mmD.O.A. 24/3/21 D.O.I. 4/5/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body & etc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5 All parts prices from USA.Owner sending veh to US for repair.10/5/21 Submit preli report -revised fig \$58,273.73 check items \$25,891.16

Date/Time, File Pass to?

☒ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 10/5/21-Typist

Report Format: OD

Lump Sum / I.B.I.: (\$

Days Of Repair: 24

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

84x24=2100250+210060322442