

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	BLUWEL AUTOMO	OTIVE SERVICE PTE LTD		Ref:	CS/TP21005403/Utf3n2	
	BLK 1 KAKI BUKIT #01-28/51/53/55(M 417883	AVE 6 AIN OFFICE)SINGAPORE		Date:	11/05/2021	
	ON BEHALF OF CL	HIANG KANG ENTERPRISES CO	MPANY PTE	Code:	TP149	
1.		Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	sured Veh.		l	GBF 3763G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From		Assign Date		03/05/2021	
2.	. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV350	c.c		2488	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JN1MC2E26Z0007216	Colour		SILVER	
	Odometer	40584 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15	TRANSIT		6 mm	
	L/H Front Tyre	195 R15	TRANSIT		6 mm	
	R/H Rear Tyre	195 R15	DUNLOP		6 mm	
	L/H Rear Tyre	195 R15	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/04/2021	Inspection Dat	е	03/05/2021	
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD				
		BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883				
5a.	Remarks					
	N)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					
	•					