



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005406/Kvf3n2	
			Date: 30/06/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 8406T	Veh. Inspected	GBF 2668E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101377/LOR	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	03/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (M)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1MC2E26Z0006357	Colour	WHITE	
Odometer	160894 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm	
R/H Rear Tyre	195 R15X8	BRIDGESTONE	8 mm	
L/H Rear Tyre	195 R15X8	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/04/2021	Inspection Date	04/05/2021	
Survey held at	HENG YAP SENG AUTO SERVICE BLK 13 SIN MENG IND. EST. SECTION B, #01-39 SINGAPORE 575657			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	