

ComfortDelGro Engineering Pte Ltd

59 Loyang Drive Singapore 508969

Our Ref	: 2054	O
		_

Via Fax

SUMPLE STANKE

Date

: 64-05-21

Your Insured

07-02-51

Attn: Motor Claims Department

Date of Acc

Dear Sirs

Time of Fax

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

A4011S

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

i) Our initial estimate of repairs of the damaged vehicle;

ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng◆ Jumani Bin Masudin

Tel: 6214 8355 or HP: 9824 0811 Tel: 6214 8315 or HP: 9635 5305

♦ Lim Tien Siong

Tel: 6214 8398 or HP: 9635 8546

◆ Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

jumanibm@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

Date: 04.05.2021

REPAIR ESTIMATE

Time: 08:16:01

Page: 1

: 305466919 : SHA4011S COMPANY: THIRD PARTY'S CLAIMS (CAS) JOB NO **CUSTOMER: 7010045** REGN NO ADDRESS: COMFORT TRANSPORTATION PTE LTD MILEAGE : 0000000000 : HYUNDAI 383 SIN MING DRIVE MAKE

SINGAPORE SINGAPORE 575717

65508755

: I-40 MODEL

DATE OF REGN : 28.04.2016 DATE/TIME IN : 03.05.2021 : 03.05.2021 10:40

ACCIDENT DATE 02.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A BUMPER W LIP & FOG LAMP C 1 1,052.20 20.00 841.76

0002 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

0003 04-01-0103-0573-A PANEL-FENDER RH+ 1 663.00 20.00 530.40

0004 04-01-0103-0640-G BRACKET-FR BUMPER SIDE RH 1 44.80 20.00 35.84

0005 04-01-0103-0658-G CAP ASSY-WHEEL HUB 1 217.20 20.00 173.76

SUB-TOTAL : 1,599.36

JOB NATURE

0000 PB	PANEL BEATING	600.00
0001 SP	SPRAYPAINT CHARGE	600.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00
0003 17-01	CHECK ALL LIGHTING	50.00
0004 20-05	RENEW ADVERTISMENT STICKER-fender	100.00

SUB-TOTAL : 1,400.00

COMFORTDELGRO ENGINEERING PTE LTD

SURVEYOR NAME & SIGNATURE

Date: 04.05.2021 Time: 08:16:01

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

305466919

REGN NO MILEAGE : SHA4011S 3 0000000000

MAKE

: HYUNDAI

MODEL

: I-40

DATE OF REGN

: 28.04.2016

DATE/TIME IN

: 03.05.2021 10:4

ACCIDENT DATE : 02.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,999.36

AUTHORISED: YES/NO

MVA NAME & SIGNATURE

DATE:

DATE:



ComfortDelGro Engineering Pte Ltd

205 Braddell Rond Singapore 579701 Mainling + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 58 Loyarig Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 04.05.2021 08:07

REGN NO.: SHA4011S

I-40

HYUNDAI

Page: 1

eam: OMER ARC Repair TP(CLSO)1

JOB CARD

JOB DESCRIPTION

Sales Order:

MAKE:

MODEL

JC NO.:305466919

E.....F

COMFORT TRANSPORTATION PTE LTD

OMER NO. FSS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

(P)

YR OF MANU. 28.04.2016

TARGET DATE

03.05.2021 10:40

MILEAGE

FUEL

CHASSIS CODE KMHLB41UMGU087877

COMPLETION DATE/TIME:

UNT CARD NO.


cident Date: 02.05.2021

TURE: 3P 02.05.2021

'NO

LABOR CODE

DESCRIPTION



9		adis 14
		REAR
-25		

) & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ment Slip

SHA4011S

JU AIG

Exit Pass

Vehicle No.:

SHA4011S

Signature/Date

Name of Service Advisor

Date

1 to Service Reception upon collection

To be kept by Security Guard

SJ0421530008 / JP Knights Pte Ltd ENTRY DATE & TIME: 03/05/2021 16:38 (SGT) SUBMITTED BY: Ashikin VERSION: 1 (03/05/2021 16:38 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6, This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 03/05/2021 16:38 (SGT)
Date of Accident 02/05/2021 10:15 (SGT)
Exact Location of Accident Upper Thomson Rd, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Hvundai

Vehicle Registration Number SHA4011S

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

1XXXXX821R

Email Address

Mobile Phone No

Alternative Phone No

Yes

COMFORT TRANSPORTATION PTE LTD

1XXXXX821R

fleetsafety@cdgtaxi.com.sg

(Phone) +65-98211775

(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer

Model
Variant

Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?
Vehicle Category
Transmission
CC

Id0

Private hire

No - Claiming third party

Manual

CC

1685

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

ThirdPartyFireTheft
Fleet Policy

Policy Number

Cover Note Number

AXA Insurance Pte Ltd
ThirdPartyFireTheft
Yes
VFX/P2419138

DRIVER

Name of Driver CHNG JOO SUM NRIC No SXXXX458C

Date Of Birth 27/09/1957 Occupation Outdoor Date Of Driving Pass 03/07/1979 Driving experience 41 YEARS AND 10 MONTHS Gender Mobile Number (Phone) +65-98211775 Alt. Phone Number Email Address fleetsafety@cdgtaxi.com.sg Address APT BLK 250 BANGKIT ROAD #05-358 Address complement Postcode 670250 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Change/cross lane Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 2/5/2021 @ 1015HRS, I WAS DRIVING MY VEHICLE A SHA4011S ALONG THOMSON ROAD ON THIRD LANE. WHILE TRAVELLING STRAIGHT, VEHICLE B SMW2483B FROM SECOND LANE, CUT INTO MY LANE AND HIT ONTO MY VEHICLE. NOBODY WAS INJURED. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Reasons for not uploading a video of the accident FILE IS NOT SUITABLE Was there any audio recorded? **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SMW2483B Vehicle Manufacturer Toyota

1

Vehicle Model

*
=
Private car
-
=:
40
-
- E
12
_
1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents finduding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to altinsurers and/or any other third pacties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the poljcyholder)

Date & Time: 3/5/2021 @ 1130 4

Reporting Coggre Personnel's Signature

Name: Name:

NRIC/FIN No.:

Mount with the Manual A-SHA 4011 S. B- 5 MW 2443 B DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
Ou 2/5/2021 @ 1015/14, I was diving	
,	
my which sha 4011 I along Thornson Rd on	
third lane while faulling stronglet, which B-	
,	-
smw 2483B from second lang, out justo my lane	1
and hit outo my which bolody was injured	
	-
	-
	\exists
	-
	-
DECLARATION If We declare the foregoing particulars are true in every hispect.	
Policyholder's Signature Driver's Signature (If driver is not the policyholder) Date & Time Oute & Time 3/5/21 - 1130H Reporting Certie Personnel's Signature Name: Name	

