

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 04.05.2021
Time: 08:16:01
Page: 1

ALG (LH)
Jm

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305466919
REGN NO : SHA4011S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.04.2016
DATE/TIME IN : 03.05.2021 10:40
ACCIDENT DATE : 02.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

<i>FRONT</i>									
0001	04-01-0103-2322-A	BUMPER W LIP & POOL LAMP	1	1,052.20	20.00	841.76	SCA		
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	na		
0003	04-01-0103-0573-A	PANEL-FENDER RH+	1	663.00	20.00	530.40	bue		
0004	04-01-0103-0640-G	BRACKET-FR BUMPER SIDE RH	1	44.80	20.00	35.84	na		
0005	04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	de		
SUB-TOTAL :								1,599.36	

JOB NATURE

0000	PB	PANEL BEATING				600.00	560		
0001	SP	SPRAYPAINT CHARGE				600.00	500		
0002	20-00	TUFF COAT ON AFFECTED PARTS.				30	50.00		
0003	17-01	CHECK ALL LIGHTING				50.00	30? X 1M		
0004	20-05	RENEW ADVERTISMENT STICKER-fender					100.00		
SUB-TOTAL :								1,400.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4 days

1599.36
1190.00
2789.36
209
2231.48
4/5-2,250