

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                           |                                                                                                       |                          |                |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|--------------------------|----------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                                  |                                                                                                       |                          |                |  |
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                                                       | Ref: CS/CTI21005451/Bqf3 |                |  |
| 3 ANSON ROAD #16-00                                                                                                                       |                                                                                                       | Date: 04/05/2021         |                |  |
| SPRINGLEAF TOWERS SINGAPORE 079909                                                                                                        |                                                                                                       | Code: CTI                |                |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                                       |                          |                |  |
| <b>Insured Veh.</b>                                                                                                                       | SLE 74T                                                                                               | <b>Veh. Inspected</b>    | SLW 7215M      |  |
| <b>Policy No.</b>                                                                                                                         | DMPCSNW00066822100                                                                                    | <b>Coverage (\$)</b>     | 0.00           |  |
| <b>Claim No.</b>                                                                                                                          | SNM21D202542/C02/LOWCT                                                                                | <b>Excess (\$)</b>       | 0.00           |  |
| <b>Assign From</b>                                                                                                                        | MERIMEN (CECILIA IOW)                                                                                 | <b>Assign Date</b>       | 04/05/2021     |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                                       |                          |                |  |
| <b>Make &amp; Model</b>                                                                                                                   | <b>c.c</b>                                                                                            |                          | 0              |  |
| <b>Engine No.</b>                                                                                                                         | HIDDEN                                                                                                | <b>Year of Reg.</b>      |                |  |
| <b>Chassis No.</b>                                                                                                                        | <b>Colour</b>                                                                                         |                          |                |  |
| <b>Odometer</b>                                                                                                                           | -                                                                                                     | <b>Steering</b>          |                |  |
| <b>Brakes</b>                                                                                                                             | <b>Modification</b>                                                                                   |                          |                |  |
| <b>General</b>                                                                                                                            |                                                                                                       |                          |                |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                                       |                          |                |  |
|                                                                                                                                           | <b>Size</b>                                                                                           | <b>Make</b>              | <b>Balance</b> |  |
| <b>R/H Front Tyre</b>                                                                                                                     |                                                                                                       |                          | mm             |  |
| <b>L/H Front Tyre</b>                                                                                                                     |                                                                                                       |                          | mm             |  |
| <b>R/H Rear Tyre</b>                                                                                                                      |                                                                                                       |                          | mm             |  |
| <b>L/H Rear Tyre</b>                                                                                                                      |                                                                                                       |                          | mm             |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                                       |                          |                |  |
|                                                                                                                                           |                                                                                                       |                          |                |  |
| <b>5. General Information</b>                                                                                                             |                                                                                                       |                          |                |  |
| <b>Accident Date</b>                                                                                                                      | 02/05/2021                                                                                            | <b>Inspection Date</b>   | 04/05/2021     |  |
| <b>Survey held at</b>                                                                                                                     | CHNG BROTHER MOTOR SERVICE<br>2 KAKI BUKIT AVENUE 2<br>#02-32 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921. |                          |                |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                                       |                          |                |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                       |                          |                |  |