

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 199007196K GS1 Reg. No. 19-9007196-K				
Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERA	L INSURANCE (S) PL	-	Ref:	CS/AGI21005455/Utf3n2
190 CLEMENCEA	J AVENUE #03-01	I	Date:	18/05/2021
		(Code:	AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMK 3411R	Veh. Inspected		SFK 52X
Policy No.		Coverage (\$)		0.00
Claim No.	C10010117/HA	Excess (\$)		0.00
Assign From	IVY RATILLA	Assign Date		04/05/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c		1987
Engine No.	HIDDEN	Year of Reg.		2010
Chassis No.	JTDGJ20WX05001994	Colour		BROWN
Odometer	366908 KM	Steering		IN ORDER
Brakes	IN ORDER	Modification		SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make		Balance
R/H Front Tyre	225/45 R17	ULTRA		6 mm
L/H Front Tyre	225/45 R17	ULTRA		6 mm
R/H Rear Tyre	225/45 R17	ULTRA		6 mm
L/H Rear Tyre	225/45 R17	ULTRA		6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/05/2021	Inspection Date	!	05/05/2021
Survey held at	AUTOMOBILE INTEGRATED MA	ANAGEMENT PTE	LTD (A	IM)
23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SINGAPORE 415933				
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SUE DAMAGES SEE D Accident Date Survey held at	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Policy Particulars Insured Veh. SMK 3411R Policy No. Claim No. C10010117/HA Assign From IVY RATILLA Vehicle Particulars Wehicle Particulars Vehicle Particulars Vehicle Particulars IN CHARLES Make & Model TOYOTA WISH (A) Engine No. HIDDEN Chassis No. JTDGJ20WX05001994 Odometer 366908 KM Brakes IN ORDER General GOOD Condition Size R/H Front Tyre 225/45 R17 L/H Front Tyre 225/45 R17 L/H Rear Tyre 225/45 R17 L/H Rear Tyre 225/45 R17 THE VEHICLE SUSTAINED DAMAGES AT THE O/S DAMAGES SEE DETAILS. General Accident Date 02/05/2021 Survey held at AUTOMOBILE INTEGRATED M. 23 KAKI BUKIT AVE 5 #04-01 (SEE) A)THE INSPECTION WAS CONDUCTED ON A"WIT B)IN ACCORDANCE TO YOUR INSTRUCTIONS, W	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Policy Particulars :- THIRD PARTY Insured Veh. SMK 3411R Veh. Inspected Policy No. Coverage (\$) Claim No. C10010117/HA Excess (\$) Assign From IVY RATILLA Assign Date Vehicle Particulars & Condition Make & Model TOYOTA WISH (A) C.c Engine No. HIDDEN Year of Reg. Chassis No. JTDGJ20WX05001994 Colour Odometer 366908 KM Steering Brakes IN ORDER Modification General GOOD Conditions of Tyres Size Make R/H Front Tyre 225/45 R17 ULTRA L/H Front Tyre 225/45 R17 ULTRA L/H Rear Tyre 225/45 R17 ULTRA Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION DAMAGES SEE DETAILS. General Information Accident Date 02/05/2021 Inspection Date Survey held at AUTOMOBILE INTEGRATED MANAGEMENT PTE 23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SIN- Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTH	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Code: Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SMK 3411R Veh. Inspected Policy No. Claim No. C10010117/HA Excess (\$) Assign From IVY RATILLA Assign Date Vehicle Particulars & Condition Make & Model TOYOTA WISH (A) c.c Engine No. HIDDEN Year of Reg. Chassis No. JTDGJ20WX05001994 Colour Odometer 366908 KM Steering Brakes IN ORDER Modification General GOOD Conditions of Tyres Size Make R/H Front Tyre 225/45 R17 ULTRA L/H Front Tyre 225/45 R17 ULTRA L/H Rear Tyre 225/4

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: