



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM21005457/Ubs3q2 Date: 13/09/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 2191M	Veh. Inspected	SLJ 1480X
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S1M039AB	Excess (\$)	0.00
	Assign From		Assign Date	04/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	CHEVROLET ORLANDO (A)	c.c	1362
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KL1YA7589HK608170	Colour	WHITE
	Odometer	67425 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	NEXEN	6 mm
	L/H Front Tyre	215/60 R16	NEXEN	6 mm
	R/H Rear Tyre	215/60 R16	NEXEN	6 mm
	L/H Rear Tyre	215/60 R16	NEXEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/05/2021	Inspection Date	04/05/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	