



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



## AUTOMOBILE INSPECTION REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21005474/T1tce2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 01-06-2021  
189556

Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SME 8457H      | Veh. Inspected | SHA 3344M  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1130181-002 | Excess (\$)    | 0.00       |
| Assign From  |                | Assign Date    | 03/05/2021 |

### 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | HYUNDAI I40       | c.c          | 1685       |
| Engine No.   | HIDDEN            | Year of Reg. | 2015       |
| Chassis No.  | KMHLB41UMGU079841 | Colour       | BLUE       |
| Odometer     | 584749            | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

### 3. Conditions of Tyres

|                | Size       | Make      | Balance |
|----------------|------------|-----------|---------|
| R/H Front Tyre | 205/60 R16 | WEST LAKE | 6 mm    |
| L/H Front Tyre | 205/60 R16 | WEST LAKE | 6 mm    |
| R/H Rear Tyre  | 205/60 R16 | WEST LAKE | 6 mm    |
| L/H Rear Tyre  | 205/60 R16 | WEST LAKE | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                |                                                                          |                 |            |
|----------------|--------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 30/04/2021                                                               | Inspection Date | 03/05/2021 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |            |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|