

Veh No:

ZM44808E Yr Rem: 2021

PAIR DETAILS

Repairer Estimates

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 May 2021)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1582U/05/05/2021 08:39

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	By *458.80 FL
2	1		*REAR DOOR APPS LOGO	0.00	0.00	el *80.00 F
Sub Total (S\$)						538.80
- List Item Discount on L Items (S\$)						91.76
Total Parts (S\$)						447.04

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC1582U/05/05/2021 08:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

80

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00
			11

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350 800.00
2	SPRAYPAINT	New	750 900.00
Gross Labour Cost (S\$)			1100 1,700.00

ComfortDelGro Engineering Pte Ltd/SHC1582U/05/05/2021 08:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

41191

Taufhi 9749 5749

2 days #

'wp' 5/5/21 4pm

2 days

Resurvey after repair

Taufhi 01/06/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s); must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: