SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 05/05/2021 12:10 (SGT) Date of Accident 04/05/2021 16:15 (SGT) Exact Location of Accident 443 Pasir Ris Drive 6, Singapore 510443 Additional Location Information **OPEN CARPARK** Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJB5689B

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner **GAN ENG KEONG** NRIC No. SXXXX383C Email Address smartoneauto@gmail.com Mobile Phone No (Phone) +65-92957986 Alternative Phone No +65-92957986

VEHICLE PARTICULARS

Manufacturer Toyota Model Corolla Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to

your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto

CC 1496

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Type of Coverage Comprehensive Fleet Policy Policy Number 2100067857-13 Cover Note Number

DRIVER

Name of Driver **GAN ENG KEONG** NRIC No. SXXXX383C

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	17/03/1963 Outdoor 26/01/1985 36 YEARS AND 4 MONTHS Male (Phone) +65-92957986 +65-92957986 smartoneauto@gmail.com BLK 491G TAMPINES STREET 45 #04-266 - 526491 Yes - No			
GENERAL INFORMATION OF THE ACCIDENT				
Type of Accident Weather Conditions Road Surface	Collision - Major/Minor Rd Clear Dry			
OTHER INFORMATION				
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 2 No - Yes 1			
DETAILS OF POLICE ACTION				
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No -			
CIRCUMSTANCES OF ACCIDENT				
PLEASE REFER TO SKETCH AND ATTACHMENT (TYPE OF AC	CCIDENT IS T/P REVERSE AND HIT INSURED)			
ATTACHMENT(S)				
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No			
DETAILS OF OTHER VEHICLE PROPERTY 1				
Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver	YN4546X Commercial vehicle			
Contact Number	-			

Address complement

Postcode	_
nsurance Company Name	_
lature Of Damage	_
Details of property damaged in accident	_
lo. Of Passenger (Including Driver)	_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time Driver's Signature (# driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A= SJB5689B

B= JN4546X

Open Carpark of

B|R 443 Pasir Ris Drive 6

Describe Circumstances of the Accident

		/
		/
		/
		/
011 311 311 311		
	/	
	Refer to Attached	
	ECIEV 10 MITOCINES	
		1 - m - m - m - m - m - m - m - m - m -
	/	
/		
7		
/		
Declaration		
We declare the foregoing particul	ars are true in every respect.	
	The second seco	
1		
/		
/ ,	1	/ / /
DO.	Dia.	all orlown
-e Gu	- Com	15 (D) (N)
Policyholder's Signature / Date &	Driver's Signature (if driver is not the policyholder) / Date	Witnessed by Reporting Centre
Time	& Time	Personnel

On 04.05.2021 at about 16:15 hours at Open Carpark of BLK 443 Pasir Ris Drive 6. I was travelling straight at the above mentioned carpark and when the front vehicle slowed down and stopped, hence I followed suit.

Suddenly, I heard a loud bang and felt an impact. When I alighted, I realised it was vehicle (B) that reversing from the loading bay, hence collided onto the left hand side portion of my vehicle (A).

Vehicle (A): SJB 5689B

Vehicle (B): YN 4546X

gen 05/05/2021

Egn















