

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                                                                                                         |                                     |            |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|-------------------------------------|------------|
| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                                         |                                     |            |
| INDIA INTERNATIONAL INSURANCE PL                                                                                                       |                                                                                                                         | Ref: <del>CS/GRB21005489/Bqf3</del> |            |
| 64 CECIL STREET                                                                                                                        |                                                                                                                         | Date: 05/05/2021                    |            |
| #05-02 IOB BUILDING SINGAPORE 049711                                                                                                   |                                                                                                                         | Code: GRB                           |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                                         |                                     |            |
| Insured Veh.                                                                                                                           | SMY 8984Y                                                                                                               | Veh. Inspected                      | SLF 4835H  |
| Policy No.                                                                                                                             |                                                                                                                         | Coverage (\$)                       | 0.00       |
| Claim No.                                                                                                                              | MFL2021D0002005                                                                                                         | Excess (\$)                         | 0.00       |
| Assign From                                                                                                                            | THAM SUI HUI                                                                                                            | Assign Date                         | 05/05/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                                         |                                     |            |
| Make & Model                                                                                                                           |                                                                                                                         | c.c                                 | 0          |
| Engine No.                                                                                                                             | HIDDEN                                                                                                                  | Year of Reg.                        |            |
| Chassis No.                                                                                                                            |                                                                                                                         | Colour                              |            |
| Odometer                                                                                                                               | -                                                                                                                       | Steering                            |            |
| Brakes                                                                                                                                 |                                                                                                                         | Modification                        |            |
| General                                                                                                                                |                                                                                                                         |                                     |            |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                                         |                                     |            |
|                                                                                                                                        | Size                                                                                                                    | Make                                | Balance    |
| R/H Front Tyre                                                                                                                         |                                                                                                                         |                                     | mm         |
| L/H Front Tyre                                                                                                                         |                                                                                                                         |                                     | mm         |
| R/H Rear Tyre                                                                                                                          |                                                                                                                         |                                     | mm         |
| L/H Rear Tyre                                                                                                                          |                                                                                                                         |                                     | mm         |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                                         |                                     |            |
|                                                                                                                                        |                                                                                                                         |                                     |            |
| <b>5. General Information</b>                                                                                                          |                                                                                                                         |                                     |            |
| Accident Date                                                                                                                          | 29/04/2021                                                                                                              | Inspection Date                     | 06/05/2021 |
| Survey held at                                                                                                                         | SZE KANG AUTOMOBILE SPRAYING SERVICES<br>BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT<br>SINGAPORE 568047 |                                     |            |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                                         |                                     |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                         |                                     |            |

CS3/GRB21005489/Bqf3