



## Estimation

Date  
Vehicle SJB 1225 H  
Make/Model HONDA ODYSSEY  
Chassis No. JHMRC1890HC203683

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAILGATE	1		\$ <del>bt</del> -
2	TAILGATE WINDSCREEN MOULDING	1	\$ 119.50	\$ <del>na</del> 119.50
3	TAILGATE WIPER MOTOR	1	\$ 642.00	\$ <del>x</del> 642.00
4	TAILGATE OUTER GARNISH	1		\$ <del>cr</del> -
5	TAILGATE LOGO - HONDA	1	\$ 57.00	\$ <del>re</del> 57.00
6	TAILGATE CENTER GARNISH - ODYSSEY	1		\$ <del>cr</del> -
7	TAILGATE LAMP L+R	2		\$ <del>cr</del> -
8	TAILGATE HANDLE OPENER	1	\$ 136.00	\$ <del>x</del> <del>cr</del> 136.00
9	TAILGATE NUMBER PLATE LAMP L+R	2	\$ 65.00	\$ <del>x</del> 130.00
10	TAILGATE LOCK	1		\$ <del>bt</del> -
11	TAILGATE LOCK CATCH	1	\$ 42.00	\$ <del>x</del> 42.00
12	TAILGATE INNER TRIM	1	\$ 225.00	\$ <del>cr</del> 225.00
13	TAILGATE HINGE L+R	1	\$ 51.00	\$ <del>x</del> 51.00
14	TAILGATE DAMPER L+R	1	\$ 175.00	\$ <del>x</del> 175.00
15	TAILGATE WEATHERSTRIP	1	\$ 153.00	\$ <del>tr</del> 153.00
16	TAIL LAMP L+R	2	\$ 360.00	\$ <del>cr</del> 720.00
17	TAIL LAMP LOWER BRACKET L+R	2	\$ 42.00	\$ <del>x</del> 84.00
18	TAIL LAMP PANEL L+R	1	\$ 202.00	\$ <del>x</del> 202.00
19	REAR SIDE BUMPER L+R	2		\$ <del>de</del> -
20	REAR SIDE BUMPER RETAINER L+R	2		\$ <del>de</del> -
21	REAR BUMPER	1		\$ <del>de</del> -
22	REAR BUMPER REVERSE SENSOR SET	4		\$ <del>nr</del> -
23	REAR BUMPER REFLECTOR L+R	2	\$ 98.00	\$ <del>nt</del> 196.00
24	REAR BUMPER REFLECTOR GARNISH L+R	2		\$ <del>de</del> -
25	REAR BUMPER RETAINER L+R	2	\$ 51.00	\$ <del>de</del> 102.00
26	REAR BUMPER BRACKET	1	\$ 89.00	\$ <del>x</del> 89.00
27	REAR BUMPER UNDERCOVER	1	\$ 302.00	\$ <del>x</del> 302.00
28	REAR FENDER L+R	2		\$ <del>x</del> -
29	REAR FENDER INNER TRIM L+R	2	\$ 518.00	\$ <del>de</del> 1,036.00
30	REAR FENDER COWLING L+R	2	\$ 192.00	\$ <del>x</del> 384.00
31	END PANEL	1		\$ <del>bt</del> -
32	END PANEL TOP GARNISH	1	\$ 255.00	\$ <del>de</del> 255.00
33	FLOOR PANEL	1		\$ <del>for buc</del> -
34	FLOOR PANEL TOP BOARD <del>MAF</del>	1	\$ 473.00	\$ <del>x</del> 473.00
35	EXHAUST PIPE	1		\$ <del>x</del> -
36	EXHAUST MOUNTING SET	2	\$ 32.00	\$ <del>x</del> 64.00
37	EXHAUST HEAT SHIELD	1	\$ 108.00	\$ <del>x</del> 108.00



				Total	\$	5,745.50
				Less 20%	\$	1,149.10
				<b>Total</b>	<b>\$</b>	<b>4,596.40</b>

	S/Nett Items					
1	TAILGATE WINDSCREEN SEALANT	1	150	\$	60 net	150.00
2	TAILGATE SPOILER CLIPS	1	100	\$	X	100.00
3	TAILGATE INNER TRIM CLIPS	1	100	\$	20 net	100.00
4	TAIL LAMP CLIPS	1	50	\$	20 net	50.00
5	TAIL LAMP PANEL SEALANT	2	120	\$	X	240.00
6	REAR BUMPER CLIPS	1	100	\$	40 net	100.00
7	REAR FENDER SEALANT	1	250	\$	X	250.00
8	REAR FENDER INNER TRIM CLIPS	2	100	\$	30 net	200.00
9	REAR FENDER COWLING CLIPS	2	100	\$	20 net	200.00
10	END PANEL SEALANT	1	200	\$	40 net	200.00
11	END PANEL TOP GARNISH CLIPS	1	100	\$	10 net	100.00
12	FLOOR PANEL SEALANT	1	300	\$	X	300.00
				<b>Total</b>	<b>\$</b>	<b>1,990.00</b>

	LABOUR					
1	PANEL BEATING ON AFFECTED AREAS	1	2400	\$	900/1000	2,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1800	\$	1200	1,800.00
3	TO RNR REAR EXHAUST	1	250	\$	80	250.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$	730 net	150.00
5	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	150	\$	530 net	150.00
6	TO RNR REAR INNER TRIM AND UPHOISTERY	1	400	\$	60	400.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	250	\$	X	250.00
8	TO RNR UNDERCARRIAGE	1	250	\$	X	250.00
9	TO CHECK WHEEL BALANCING	1	250	\$	X	250.00
10	TO CHECK WATER LEAK	1	150	\$	30	150.00
11	TO RNR FUEL TANK	1	250	\$	X	250.00
12	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$	X	600.00
13	TO RNR REAR TAILGATE MECHANISM	1	350	\$	60	350.00
14	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$	50	150.00
15	TO PERFORM RUST PROOFING	1	200	\$	40	200.00

<b>Total Labour</b>	<b>\$</b>	<b>7,600.00</b>
<b>Parts Replacement Amount</b>	<b>\$</b>	<b>6,586.40</b>
<b>Total Amount</b>	<b>\$</b>	<b>14,186.40</b>

Tauplin 97495749  
 WP 6/8/21 @ 3:15pm  
 L/S Rusty after repair  
 Tauplin @ 11 hours  
 7 days

**LKK Auto Consultants** hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 687C

### Vehicle Details

Vehicle No.: SJB1225H

Vehicle to be Exported: No

Intended Deregistration Date: 31 May 2021

Vehicle Make: HONDA

Vehicle Model: ODYSSEY 2.4 EXV-S CVT SR

Primary Colour: Purple

Manufacturing Year: 2017

Engine No.: K24W72041329

Chassis No.: JHMRC1890HC203683

Maximum Power Output: 129.0 kW (172 bhp)

Open Market Value: \$30,986.00

Original Registration Date: 09 Oct 2017

First Registration Date: 09 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$35,381.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Oct 2027

PARF Rebate Amount: \$26,535.00

### Intended COE Rebate Details

COE Expiry Date: 08 Oct 2027

COE Category: B - Car above 1600cc or 97kW  
(130bhp)

COE Period(Years): 10

QP Paid: \$49,189.00

COE Rebate Amount: \$31,258.00

**Total Rebate Amount: \$57,793.00**

The information contained herein is correct as at 03 May 2021

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/05/2021 15:55 (SGT)
Date of Accident	01/05/2021 12:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	LOWER DELTA ROAD BEFORE BUKIT PURMEI
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB1225H
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN SUAN FOONG
NRIC No	SXXXX687C
Email Address	EVANTANSF@GMAIL.COM
Mobile Phone No	(Phone) +65-97373569
Alternative Phone No	+65-97373569

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2400

#### INSURANCE COMPANY

Name of Insurance Company	Aviva Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	10782408
Cover Note Number	-

#### DRIVER

Name of Driver	TAN SUAN FOONG
NRIC No	SXXXX687C



Date Of Birth	11/11/1971
Occupation	Indoor
Date Of Driving Pass	24/02/1994
Driving experience	27 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97373569
Alt. Phone Number	+65-97373569
Email Address	EVANTANSF@GMAIL.COM
Address	151 CAVENAGH RD
Address complement	#02-153
Postcode	229628
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG2636Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Postcode	-
Insurance Company Name	-
Nature Of Damage	FRONT & REAR
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMY9150E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	FRONT PORTIONS
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

## SKETCH PLAN


## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

## Sketch Plan



Lower Batta Rd at Bukit Rumei Rd

Vehicle A: 5JB1225H  
Vehicle B: 9L62636Z  
Vehicle C: 5MY9150E



Describe Circumstances of the Accident

On the stated date and time I was travelling along the stated location on my vehicle A. As my vehicle slowed down for the traffic light I suddenly felt an impact from my vehicle rear, vehicle B had collided into my vehicle rear portion with his vehicle front. When I alighted to check, I realised I was involved in a 3 car chain collision and I was the first vehicle.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel