

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG Code: ASM 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SH 8307X Veh. Inspected SGW 2299M Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M039CH Excess (\$) 0.00 Assign From Assign Date 05/05/2021 2. Vehicle Particulars & Condition Make & Model HONDA CIVIC c.c 1597 Engine No. HIDDEN Year of Reg. 2018 Chassis No. MRHFC5650JT000780 Colour MULTI COLOUR Odometer 46660 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres R/H Front Tyre 235/35 R18 MICHELIN 6 mm L/H Front Tyre 235/35 R18 MICHELIN 6 mm R/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	Affiliated to Federation Internationale Des Experts En Automobile					
AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG Code: ASM 1.	AXA INSURANCE F	PTE LTD	_	Ref:	CC4/ASM21005497/T1pa3q2	
Insured Veh. SH 8307X				Date:	11/10/2021	
Insured Veh. SH 8307X	ATTN:RICHARD AN	IG		Code:	ASM	
Policy No.	1. Policy Particulars :- THIRD PARTY CLAIM					
Claim No. S1M039CH Excess (\$) 0.00 Assign From Assign Date 05/05/2021	Insured Veh.	SH 8307X	Veh. Inspected		SGW 2299M	
Assign From	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
2. Vehicle Particulars & Condition Make & Model	Claim No.	S1M039CH	Excess (\$)		0.00	
Make & Model	Assign From		Assign Date		05/05/2021	
Engine No. HIDDEN Chassis No. MRHFC5650JT000780 Colour MULTI COLOUR Odometer 46660 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres Size Make Balance R/H Front Tyre 235/35 R18 MICHELIN 6 mm L/H Front Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre A. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	2. Vehicle Particulars & Condition					
Chassis No. MRHFC5650JT000780 Colour MULTI COLOUR Odometer 46660 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance R/H Front Tyre 235/35 R18 MICHELIN 6 mm L/H Front Tyre 235/35 R18 MICHELIN 6 mm R/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	Make & Model	HONDA CIVIC	c.c		1597	
Odometer 46660 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres Size Make Balance R/H Front Tyre 235/35 R18 MICHELIN 6 mm L/H Front Tyre 235/35 R18 MICHELIN 6 mm R/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	Engine No.	HIDDEN	Year of Reg.		2018	
Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance R/H Front Tyre 235/35 R18 MICHELIN 6 mm L/H Front Tyre 235/35 R18 MICHELIN 6 mm R/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	Chassis No.	MRHFC5650JT000780	Colour		MULTI COLOUR	
General GOOD 3. Conditions of Tyres Size Make Balance	Odometer	46660 KM	Steering		IN ORDER	
3. Conditions of Tyres Size Make Balance	Brakes	IN ORDER	Modification		SPORTS RIM	
Size Make Balance	General	GOOD				
R/H Front Tyre 235/35 R18 MICHELIN 6 mm L/H Front Tyre 235/35 R18 MICHELIN 6 mm R/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	3. Conditions of Tyres					
L/H Front Tyre 235/35 R18 MICHELIN 6 mm R/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.		Size	Make		Balance	
R/H Rear Tyre 235/35 R18 MICHELIN 6 mm L/H Rear Tyre 235/35 R18 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	R/H Front Tyre	235/35 R18	MICHELIN		6 mm	
L/H Rear Tyre 235/35 R18 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	L/H Front Tyre	235/35 R18	MICHELIN		6 mm	
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	R/H Rear Tyre	235/35 R18	MICHELIN		6 mm	
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.	L/H Rear Tyre	235/35 R18	MICHELIN		6 mm	
DAMAGES SEE DETAILS.						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.					
	DAMAGES SEE DETAILS.					
5. General Information	5.					
Accident Date 01/05/2021 Inspection Date 06/05/2021	Accident Date	01/05/2021	Inspection Date)	06/05/2021	
Survey held at RICO 60 AUTO SERVICES PTE LTD	Survey held at	RICO 60 AUTO SERVICES PTE	LTD			
8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		#02-24 PREMIER @ KAKI BUKIT				
5a. Remarks						
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b. Estimate Days of Repair						
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days	ESTIMATED NORM					