

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Nissan Nv350 (GBD3853R)
Date of Loss	1 May 2021
Time of Loss	21:20
Loss Description	SFQ8801S (INSD) HIT REAR OF GBD3853R (TP)
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	-\$10,567.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# GBD3853R

Registration State SINGAPORE

Mileage 79559

Purchase Date DD/MM/YYYY



Registration Date * 29/09/2014



Age of Vehicle 6

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2014

Driver Details

CATEGORY



FNOL
INFORMATION

POST SURVEY INFORMATION


Driver Name

GAN CHOY
HAA

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Nissan	<input type="text" value="NISSAN"/>
Model	Nv350	<input type="text" value="NV350 PANEL VAN 2.5 !"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JN1MC2E26Z0003093"/>
Engine No		<input type="text" value="YD25355614A"/>
Engine Capacity		<input type="text" value="2488"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	31 December 1899	<input type="text" value="DD/MM/YYYY"/> 
Age	121	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address		<input type="text"/>
Address type		<input type="text" value=""/>
Gender	Unknown	<input type="text" value=""/>
Marital status	Unknown	<input type="text" value=""/>
Identification #	S7973085H	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

11/05/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

195 R15X8

BRIDGESTONE7mm

BRIDGESTONE7mm

195 R15X8

BRIDGESTONE8mm

BRIDGESTONE8mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition








Taxes & Ratio












Parts & Labour

Miscellaneous















Summary

Parts

Add		Approve		Deny	Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER	Buckled	0	600.5	No	0	10	0	0	540.45
	0	1		REAR BUMPER STEP BEAM	Repair	0	0	No	0	0	0	0	0
	0	1		TAIL LAMP O/S	Cracked	0	209.8	No	0	10	0	0	188.82
	0	1		TAIL LAMP N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE	Bent	0	2101.4	No	0	10	0	0	1891.26
	0	1		TAILGATE OUTER CHROME HANDLE	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE "NV350" EMBLEM	Necessary	0	50.4	No	0	10	0	0	45.36

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILGATE "URVAN" EMBLEM	Necessary	0	59.7	No	0	10	0	0	53.73
	0	1		TAILGATE CENTRE LOGO	Necessary	0	59.7	No	0	10	0	0	53.73
	0	1		TAILGATE LOCK	Repair	0	0	No	0	0	0	0	0
	0	2		TAILGATE DAMPERS	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE WEATHERSTRIP	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE INNER TRIM BOARD	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER RH	Repair	0	0	No	0	0	0	0	0
	0	1		REAR END PANEL (OUTER)	Bent	0	152.4	No	0	10	0	0	137.16
	0	1		REAR END PANEL (INNER)	Repair	0	0	No	0	0	0	0	0
	0	1		REAR FLOOR PANEL	Repair	0	0	No	0	0	0	0	0
	0	1		REAR SPARE TYRE HANGER	Repair	0	0	No	0	0	0	0	0

Labour

Add		Approve		Deny		Submit All				
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		LABOUR CHARGE TO REMOVE, CUT OUT, DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	0	900	0	0	Reviewing		
	0		TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	0	800	0	0	Reviewing		
	0		TO REMOVE, REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR	0	60	0	0	Reviewing		
	0		TO REMOVE, REPLACE REVERSE SENSOR	0	50	0	0	Reviewing		
	0		TO REMOVE, REPLACE SPARE TYRE HANGER	0	0	0	0	Deny		
	0		TO REMOVE, REPLACE REAR EXHAUST SILENCER	0	0	0	0	Deny		
	0		TO CHECK WIRING AND LIGHTINGS	0	20	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 6 DAYS	Reviewing	0	0		
	0	REAR NUMBER PLATE	Deny	0	0	SERVICEABLE	
	0	REVERSE SENSOR (2PCS)	Deny	0	0	SERVICEABLE	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$4,740.51
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$2,910.51
Labour	\$0.00	\$1,830.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

3800





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$3,800.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$3,800.00

Submit for Review