

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMF1669D*at Workshop m/s *hockeuch*

of _____

Insured: *SJA 13432*

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *666k.*

IDAC Accident Report: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: *3*

days

Res.: Yes or No

Lum Sum: *1.51*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: *Rep. SJA*

Date / Time

Action / Instruction

*LTA \$31099*Veh No: *SMF1669D*Yr Regn: *30/10/18*Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA /*Make: *Nissan Sylphy*c.c. *1528*Colour: *white*

A/C:

Insured / Std / NI / NA

Sp. Reading: *11029*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *MNTBBAB1720032253*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Good* / Jammed / Leaked / Burnt orBrake: *Good* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: *F: 205/55R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU *PR* / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. *7*

mm

R/Bal. *7*

mm

L/Bal. *7*

mm

L/Bal. *7*

mm

D.O.A. *29/4/11*D.O.I. *30/5/11*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

) S + RS. SI _____

☐

: Interview (\$ _____)

) Photos _____

☐

: Tech. Invs (\$ _____)

) Others _____

☐

: Weekend (\$ _____)

) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

9/6/11 continued 9/12 & 11/5/11 with Anger

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: SXXX7513C
PHANG SIAN NEN
NO

SINGAPORE
TEL: FAX:
PH: 81186863
ATTN:

ESTIMATE BILL

Number: EB00005690
Date: 03/05/2021
Case No: AD00011771
Vehicle No: SMF1669D
Chassis: MNTBBAB17Z0032752
Year of Mfr: 2018
Policy No:
Model: NISSAN SYLPHY 1.6
CVT

Term:

not item

Nett

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BUMPER <i>50/22</i>	1.0	670.00	10	603.00
2	REAR BUMPER RETAINER RH <i>8u</i>	1.0	36.30	10	32.67
3	REAR BUMPER REFLECTOR RH <i>11</i>	1.0	65.00	10	58.50
Nett Price - Parts Sub Total					694.17
4	REAR FENDER RH - REPAIR <i>11 X</i>				
5	BOOTLID - REPAIR <i>11 X</i>	1.0			
6	REVERSE SENSOR <i>11</i>	1.0	280.00	0	280.00
Special Nett Price - Parts Sub Total					280.00
Parts Total					974.17
7	LABOUR TO REMOVE & REFIT NECESSARY PARTS <i>200</i>	1.0	800.00	0	800.00
8	SPRAY PAINT ON THE AFFECTED AREAS <i>300</i>	1.0	800.00	0	800.00
9	ANTI-RUST COATING <i>11 X</i>	1.0	150.00	0	150.00
10	TO REMOVE & REFIT REVERSE SENSOR <i>50</i>	1.0	150.00	0	150.00
Labour 1 Sub Total					1,900.00
<i>not Authorised</i> <i>Law</i> <i>31/5/21</i> <i>Take the before party.</i> <i>3 days.</i> <i>2/12/153</i>					
KK Auto Consultants hereby notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company					
Acknowledged by Repairer Signature					
SINGAPORE DOLLARS: THREE THOUSAND SEVENTY-FIVE AND CENTS THIRTY-SIX ONLY					
Date:					
Less Excess					0.00
SUBTOTAL					2,874.17
GST 7.00%					201.19
TOTAL					3,075.36

Date of accident : 29/04/2021 03:05 PM. Place : SLIP ROAD OF QUEENSWAY > ALEXANDRA ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST