

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAI	L INSURANCE (S) PL	R	Ref:	CS/AGI21005530/Kuf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	oate:	25/08/2021	
			C	ode:	AGI	
1.		Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMR 5888Z	Veh. Inspected		SJB 2681S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010126/HA	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		06/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CIVIC (A)	c.c		1799	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	JHMFD16308S211286	Colour		METALLIC GREY	
	Odometer	525815 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	PIRELLI		7 mm	
	L/H Front Tyre	225/45 R17	PIRELLI		7 mm	
	R/H Rear Tyre	225/45 R17	PIRELLI		7 mm	
	L/H Rear Tyre	225/45 R17	PIRELLI		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE.					
	DAMAGES SEE D	DAMAGES SEE DETAILS.				
5.	General Information					
	Accident Date	04/05/2021	Inspection Date		12/05/2021	
	Survey held at	GUAN HIN MOTOR WORKSHOP				
		BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				