

ASS. REF. BY:

REF:

CS/AGI21005530/Kuf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OO/TP/INS/TP RES/CO RES/EVA/INV/INV

To inspect Vehicle No: SJB 2681S

at Workshop m/s:

of

Insured:

SMR 5888Z

Policy No:

Claims No:

C10010126/HA

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Veh No:

SJB 2681S

Yr Regn:

01, 08

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic cc 1799

Colour:

M. Grey

AC:

Insured / Std / NI / NA

Sp. Reading:

525815

T/Radio:

Insured / Std / NI / NA

Eng No:

G.No:

JHMF0183085211286

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD / A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Sal:

7

mm

R/Sal:

7

mm

L/Sal:

7

mm

L/Sal:

7

mm

D.O.A.

4/5/21

D.O.I.

12/5/2021

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S R & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirmed final fig L/S \$2000, 3 repair days.

(RED \$1866: 48%)

Data/Time, File Pass to?

☐

: Prel. Report

1) 23/8 TYPIST

☐

: Final Report

Data/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Transporter:

S + RS \$

: Fares

: Other

Report Format:

TP

Lump Sum / L/S (\$ 2000

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A
#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221
E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924

Attention : Motor Claim Department
Contact : 62212111

Estimate : ES000940

Date : 12/05/2021

Vehicle Num. : SJB 2681 S

Make/Model : HONDA CIVIC 1.8LA-2007

Chassis/Eng# : JHMFD16308S21186/R18A13018390

Accident Date : 04/05/2021

Claim No. :

Reference :

Policy No. : (07/01/2008)

*Not Authored
L/Sing @
Resurvey After Pain 3 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|-------------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | FRONT BUMPER | | |
| 3. | 1 | FRONT BUMPER SIDE RETAINER LH | | |
| 4. | 1 | FRONT LH FENDER INNER SHIELD | | |
| 5. | 1 | FRONT LH LOWER ARM | | |
| 6. | 1 | FRONT LH SHOCK ABSORBER | | |
| 7. | 1 | FRONT KNUCKLE ARM BEARING LH | | |
| 8. | 1 | FRONT LH KNUCKLE ARM | | |

Not Com
638.00
45.00
cm 150.00
243.00
259.00
166.00
305.00

List Total S\$:

1,806.00

- | | | | | |
|----|----|--------------------------|--|--|
| 1. | 1 | SPECIAL NETT ITEMS : | | |
| 2. | 1 | TYRE | | |
| 3. | 10 | SPORT RIM | | |
| | | FENDER INNER SHIELD CLIP | | |

Sum 380.00 X
Red 480.00 ✓
me 20.00 ✓

Special Nett Total S\$:

880.00

LABOUR :
REMOVE & FIX BACK FRONT BUMPER AND INNER SHIELD

2001
250.00

REMOVE & FIX BACK UNDERCARRIAGE

450.00 7

WHEEL ALIGNMENT

180.00 601

SPRAY PAINTING

300.00 2001

Labour Total S\$:

1,180.00

E. & O.E.

Total S\$: 3,866.00



for GUAN HIN MOTOR WORKSHOP

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



3D WHEEL ALIGNMENT REPORT

Date : 05/12/2021 10:21:01

Customer Name : GUAN HIN

Description : HONDA CIVIC

Plate NO. : SJB2681S Kilometers :0

	Previous Values		Final Values		Databank Values		
	LH	RH	LH	RH	MIN		MAX
Front Axle							
Total Toe	0° 18'		0° 22'		-0° 10'	0° 2'	0° 14'
Half Toe In	0° 19'	-0° 1'	0° 21'	0° 1'	-0° 5'	0° 1'	0° 7'
Camber	-1° 10'	-0° 15'	-2° 35'	-0° 16'	-0° 29'	0° 1'	0° 31'
Caster	7° 30'	5° 54'	7° 20'	5° 54'	6° 11'	6° 56'	7° 41'
King-pin angle	7° 9'	3° 5'	8° 34'	3° 5'	-		-
Included Angle	5° 59'	2° 50'	5° 58'	2° 50'			
Steering angle diff at 20°	0° 0'	0° 0'	0° 0'	0° 0'			
Max Steering Angle	0° 0'	0° 0'	0° 0'	0° 0'			
Set-Back	0° 0'		0° 4'				
Rear Axle							
	LH	RH	LH	RH	MIN		MAX
Total Toe	0° 4'		0° 4'		-0° 4'	0° 8'	0° 20'
Half Toe In	-0° 4'	0° 8'	-0° 1'	0° 5'	-0° 2'	0° 4'	0° 10'
Camber	-1° 58'	-1° 58'	-1° 58'	-1° 57'	-2° 24'	-1° 24'	-0° 24'
Set-Back	0° 6'		0° 8'				
Thrust Angle	-0° 6'		-0° 3'				

STAMFORD TYRES INTERNATIONAL P/L

Address:NO 10 ANG MO KIO IND PARK 2A #01-14

Contacter:

Tel: 65 6483 3355,6555 5636

Fax:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/05/2021 10:05 (SGT)
Date of Accident	04/05/2021 10:45 (SGT)
Exact Location of Accident	Jln Eunus, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB2681S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN HWA HOON @ NEO KWA HOON
NRIC No	SXXXX104B
Email Address	kpetan@singnet.com.sg
Mobile Phone No	(Phone) +65-90011142
Alternative Phone No	+65-90011142

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Civic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1799


INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	5106304424-02
Cover Note Number	-

DRIVER

Name of Driver	TAN HWA HOON @ NEO KWA HOON
NRIC No	SXXXX104B

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the date 4/5/2021, I was travelling along Jalan Eunus. This vehicle SMR5288Z came out from this condo euhabitat without stopping and drive out to the road, I quickly apply my brake to avoid it but my car swipe to Ltl and hit onto the road kerb. my car sustain front Ltl and undercarriage damage.

I wish to stat that because of the driver caused this accident.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:

NRIC/IN No.:
05.05.2021