

Our Job Ref No : 305467302
Date : 06/05/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHA2808Z

Date of Accident : 05/05/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SML4365D
###
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$976.12
 - (b) Labour Charges \$641.00
 - Total for Part-By-Part Repair Cost** \$1,617.12
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : taufikh
Name : Taufikh
Date : 27/5/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	--	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305467302
REGN NO : SHA2808Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 06.08.2020
DATE/TIME IN : 05.05.2021 10:10
ACCIDENT DATE : 05.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	2.00-	180.00
0004 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0005 FNPS	NUMBER PLATE FRONT W/CASI	1 N	50.00	2.00-	50.00

SUB-TOTAL : 976.12

JOB NATURE

0000 PB	PANEL BEATING	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00
0003 L	MERIMEN FEE	11.00

SUB-TOTAL : 641.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 06.05.2021

REPAIR ESTIMATE

Time: 16:36:52

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305467302
REGN NO : SHA2808Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 06.08.2020
DATE/TIME IN : 05.05.2021 10:1
ACCIDENT DATE : 05.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,617.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 06 May 2021)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA2808Z/06/05/2021 16:38**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr		Amount
1	1		*REVERSE SENSOR	0.00	0.00	nw ✓	*180.00 F
F=Franchise part.							
Total Parts (\$\$)							180.00

ComfortDelGro Engineering Pte Ltd/SHA2808Z/06/05/2021 16:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SHA2808Z/06/05/2021 16:38. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

(SUPPLEMENTARY)

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
LUMENS AUTO PTE. LTD.

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	ML000509	Date of Loss:	05/05/2021
Vehicle Reg. No.:	SHA2808Z	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	06/08/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU412282	Chassis No:	KMHC851CVLU190836
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	180.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	180.00
+ GST 7.00% (\$)	12.60
Nett Amount (\$)	192.60
+ Previous Estimates (\$)	2,074.86
Claim Total (\$)	2,267.46

Generated using Merimen e-Claims Internet Estimation & Adjusting System